

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

Product Name	X11SCW-F
Release Version	1.5a
Release Date	3/23/2021
Build Date	3/23/2021
Previous Version	1.5
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none"><li>1. Changed the BIOS version to 1.5a.</li><li>2. Updated SPS firmware to SPS_E3_05.01.04.300.0 for IPU 2021.1 for INTEL-SA-00459 Security Advisory to address CVE-2020-24509 (6.7, Medium), CVE-2020-8704 (6.7, Medium), CVE-2020-24507 (6.0, Medium), CVE-2020-8703 (5.1, Medium), and CVE-2020-24506 (4.4, Medium) security issues.</li><li>3. Copied the BIOS binary and renamed it to meet the unique name format.</li><li>4. Updated microcodes M02906EB_000000EA (B-0 Stepping), M22906EC_000000EA (P-0 Stepping), and M22906ED_000000EA (R-0 Stepping) for Intel 20211IPU for INTEL-SA-00464 Security Advisory to address CVE-2020-24511 (5.6, Medium) and CVE-2020-24512 (2.8, Low) security issues.</li><li>5. Adjust the ME power on sequence.</li></ol>

<b>New features</b>	N/A
<b>Fixes</b>	<b>1. Fixed failure of SUM test 220 due to "PCI AER Support" and "Memory Corrected Error Enabling" setting failing to preserve after flashing BIOS.</b>

**Release Notes from Previous Release(s)**

**1.5 (10/12/2020)**

1. Added inband flash status event log to IPMI MEL.
2. Added Hotkey Message Enable/Disable function.
3. Updated SPS firmware to SPS\_E3\_05.01.04.208.0 for INTEL-TA-00391 Security Advisory to address CVE-2020-8744 (7.2, High) and CVE-2020-8755 (4.6, Medium) security issues.
4. Updated microcodes M22906EA\_000000DE (U-0 Stepping), M02906EB\_000000DD\_000000DE (B-0 Stepping), M22906EC\_000000DE (P-0 Stepping), and M22906ED\_000000DE (R-0 Stepping) for Intel IPU 2020.2.
5. Updated Intel IPU 2020.2 RC 7.0.58.47 for Mehlow Refresh Server Platform Service Version.
6. Changed the BIOS version to 1.5.
7. Enhanced SMCI HDD Security feature.
8. Removed the FWSTS SMBIOS table.
9. Updated CmosManager\_09 and SecureFlash\_23 for AMI-SA50081 Security Update.
10. Reduced Rowhammer susceptibility for AMI-SA50084 DDR4 Rowhammer vulnerability to address CVE-2020-10255 (9.0, high) security issue.
11. Added use of Intrusion SMI to notify BMC the system has chassis intrusion.
12. Fixed problem of BIOS setup menu showing "Unknown" when plugging in the InnoDisk memory and boot up into BIOS setup menu.

**1.4 (5/26/2020)**

1. Changed the BIOS version to 1.4.
2. Implemented IPU 2020.1 update to SPS firmware to SPS\_E3\_05.01.04.113.0.
3. Enhanced the OEM FID feature to support UUID.
4. Updated Intel RSTe RAID Option ROM/UEFI Driver to 6.3.0.1005.
5. Added SMCI HDD Security feature.
6. Updated microcodes M22906EA\_000000D6 (U-0 Stepping), M02906EB\_000000D6 (B-0 Stepping), M22906EC\_000000D6 (P-0 Stepping), and M22906ED\_000000D6 (R-0 Stepping) for INTEL-SA-00320 Security Advisory to address CVE-2020-0543 (6.5, High) security issue, and microcodes M22906EA\_000000D6 (U-0 Stepping), M02906EB\_000000D6 (B-0 Stepping), M22906EC\_000000D6 (P-0 Stepping), and M22906ED\_000000D6 (R-0 Stepping) for INTEL-SA-00329 Security Advisory to address CVE-2020-0548 (2.8, Low) and CVE-2020-0549 (6.5, Medium) security issues.
7. Set the OverclockingLock flag to enabled by default for SGX test.
8. Added support for InnoDisk memory.
9. Added use of BIOS setup menu to enable/disable LAN1/LAN2 feature.
10. Fixed inability to change the serial port IO resource.
11. Fixed failure of Secure Erase password and problem of BIOS returning "EFI\_Device\_Error" with SED: Seagate ST1000NX0353.

**1.3 (2/20/2020)**

1. Changed the BIOS version to 1.3.
2. Updated BiosAcm to 1.7.1 (20191213) and SinitAcm to 1.7.8 (20191220) for INTEL-SA-00240 to address CVE-2019-0151 (7.5, High) and CVE-2019-0152 (8.2, High), for INTEL-SA-00220 to address CVE-2018-0123 (8.2, High) and CVE-2019-0124 (8.2, High), and INTEL-SA-00164 to address CVE-2019-0184 (6.0, Medium).

3. Added solution for problem of systems with LPDDR3 2133 MT/s DRAMs failing during boot.
4. Corrected the "DeepSx Power Policies" item string.
5. Updated RC to Mehlow Refresh PV version 7.0.58.44.
6. Displayed the "SGX Launch Control Policy" items in the BIOS setup menu.
7. Added SMC HDD Security feature.
8. Updated Microcodes M22906EA\_000000D2 (U-0 Stepping), M02906EB\_000000D2 (B-0 Stepping), M22906EC\_000000D2 (P-0 Stepping), and M22906ED\_000000D2 (R-0 Stepping) for INTEL-SA-00320 Security Advisory to address CVE-2020-0543 (6.5, High) security issue and for INTEL-SA-00329 Security Advisory to address CVE-2020-0548 (2.8, Low) and CVE-2020-0549 (6.5, Medium) security issue.
9. Updated flag for skipping password prompt window.
10. Fixed inability of BIOS to load default when plugging in M.2.
11. Added support for erasing NVMe Opal device (like Samsung 970 EVO model MZ-V7E250) without setting admin password.

### **1.2 (10/24/2019)**

1. Changed BIOS version to 1.2.
2. Added support for BMC AUX revision displaying.
3. Disabled the MCTP for buggy BMC workaround.
4. Updated Microcode M22906EA\_000000C6 (U-0 Stepping), M02906EB\_000000C6 (B-0 Stepping), Microcode M22906EC\_000000C6 (P-0 Stepping), and M22906ED\_000000C6 (R-0 Stepping) for INTEL-SA-00270 Security Advisory to address CVE-2019-11135 (6.5, Medium) security issue.
5. Updated the SINIT ACM to version 1.7.3 for INTEL-SA-00220 Security Advisory to address CVE-2018-0123 (8.2, High) and CVE-2019-0124 (8.2, High) security issues.
6. Updated SPS firmware to SPS\_E3\_05.01.03.094.0.
7. Updated the Intel PMC firmware to 300.2.11.1022.
8. Updated the AMI TSE to 2.20.1276.
9. Updated RC to Mehlow Refresh PV version 7.0.58.43 for INTEL-SA-00260 Security Advisory to address CVE-2019-0154 (6.5, Medium) security issue.
10. Updated NVRAM NVMe HddSecurity SmmConfidentialMemModule and TcgStorageSecurity to INTEL-SA-00254 request version for INTEL-SA-00254 Security Advisory to address CVE-2019-0185 (6.0, Medium) security issue.

### **1.0b (5/16/2019)**

1. Added support for Linux built-in utility efibootmgr.
2. Added support for consistent device naming for on-board devices.
3. Updated OOB module to R.1.0.1.3
4. Hid the item "Always Turbo Mode" after setting the "Turbo Mode" to disabled in Advanced/CPU Configuration page.
5. Added OEM strings to 50 bytes in type 11.
6. Added "Driver Health setup" item.
7. Added driver health warning message.
8. Renamed "AC Loss Policy Depend on" to "Restore on AC Power Loss".
9. Enhanced the solution for the error/warning message from dmidecode after AMIDE modification.
10. Enhanced Error logging for SD5.
11. Updated Coffee Lake-S R-0 stepping CPU microcode M22906ED\_000000B4.

- 12. Updated SPS 5.1.03.62 for INTEL-SA-00213 Security Advisory to address CVE-2019-0089, CVE-2019-0090, CVE-2019-0086, CVE-2019-0091, CVE-2019-0092, CVE-2019-0093, CVE-2019-0094, CVE-2019-0096, CVE-2019-0097, CVE-2019-0098, and CVE-2019-0099.
- 13. Exposed the CPU's PL1 and PL2 items of Advanced -> CPU Configuration page in the BIOS setup menu.
- 14. Updated Intel RSTe RAID Option ROM/UEFI Driver to 6.1.0.1017.
- 15. Updated MCU 906EA-U0 + 906EB-B0 + 906EC-P0) for INTEL-SA-00233 Security Advisory to address CVE-2018-12126, CVE-2018-12127, and CVE-2018-12130.
- 16. Updated RC to version 7.0.58.41 to support 32GB of memory.
- 17. Updated USB and Fastboot module.
- 18. Set default setting Power Limit 2 to 150W when 8 Core CPU is used in the system.
- 19. Set OptionRom and boot mode select to EFI while CSM is disabled.
- 20. Changed UEFI LAN Boot option name format for SUM requirement.
- 21. Added RFC3021 solution for the network stack (/32 subnet mask support).
- 22. Fixed malfunction of SR-IOV feature.
- 23. Updated "Restore Optimized Defaults" string for Mehlow Server template.
- 24. Modified UEFI network description to IPv4/IPv6 to follow Industry Standard.
- 25. Removed processor version "Type" string for Mehlow Server template.
- 26. Added a Disabled option for "Onboard Video Option ROM" setup item.
- 27. Updated "Redirection After BIOS POST" string for Mehlow Server template.
- 28. Fixed problem of BMC VGA status being enabled in SMBIOS Type 41 when JPG1 is disabled (In 2-3).
- 29. Fixed lack of onboard VGA information in Type 40.
- 30. Fixed problem of DIMM location showing "NO DIMM INFO" in Event log when ECC error occurs.
- 31. Fixed problem of DIMM location always showing "DIMMA1" in BIOS Event log when ECC error occurs.
- 32. Fixed problem of the POST screen showing "?[1;31;40m" when EFI driver is "Unhealthy".
- 33. Fixed issue of system may or may not hanging up when LAN1 is disabled.

### **1.0a (12/24/2018)**

- 1. Updated BIOS revision to 1.0a.
- 2. Updated Intel Reference Code to version 7.0.48.21.
- 3. Updated CPU MCUs (906EA, U0 + 906EB, B0 + 906EC, and P0).
- 4. Hid LAN OPROM Control items besides LAN#1 when LAN#1 OPROM is set to iSCSI.
- 5. Added Early Video messages when BIOS is in recovery mode.
- 6. Added "ACPI T-States" setup item.
- 7. Displayed "AERON" and "MCEON" strings during POST when "PCI AER Support" or "Memory Corrected Error" is enabled.
- 8. Hid "ECC Support" item.
- 9. Set the default of "Memory Corrected Error Enabling" to disabled.
- 10. Updated the Intel BIOS ACM version to 1.5.0 and SINIT ACM to 1.6.0.
- 11. Added "SMC SMBIOS Measurement" feature for PCR#1 measurement and enabled "Measure\_Smbios\_Tables".
- 12. Updated RAID option ROM and UEFI driver to 5.5.1028.
- 13. Added "MCEON" and "AERON" POST strings for SOL console when items are enabled.
- 14. Enhanced JPG1 function for running SUM with JPG1 2-3.
- 15. Added support for RFC4122 UUID format feature so that RFC4122 encoding from build time is produced by IPMICFG 1.29 tool or newer version.

- 16. Added SATA Frozen function.
- 17. Updated SPS firmware to SPS\_E3\_05.00.03.114.
- 18. Added support for Linux built-in utility efibootmgr.
- 19. Fixed inability of Boot Option of UEFI Application Boot Priorities to load default via Afu tool with command "/N".
- 20. Changed "Sata Interrupt Selection" default value to MSI.
- 21. Fixed problem of the status of Chassis Intru clearing in every single boot.
- 22. Fixed problem of serial port UID order not following COM port order after BIOS update.
- 23. Fixed problem of PCR#1 value changing during Legacy boot with TPM 2.0 when Measure\_Smbios\_Tables is disabled.
- 24. Fixed problem of the system having an exception while entering BIOS Setup with NVMe M2\*1 + SATA M2\*1.
- 25. Fixed problem of InBand receiving incorrect OEM FID size.
- 26. Fixed inability to show RSC-W-68 information when only RSC-W-68 is plugged in the SMBIOS.