

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSG-AN6
Release Version	00.01.06
Release Date	3/16/2022
Previous Version	00.01.04
Update Category	Recommended
Dependencies	BIOS R 2.2
Important Notes	<p>IPMI Image: BCM_H12SSG-AN6-AST2600-ROT1PLUS-9301MS_20220316_00.01.06_STDsp.bin</p> <p>IPMI Update Package: BCM_H12SSG-AN6-AST2600-ROT1PLUS-9301MS_20220316_00.01.06_STDsp.zip</p>
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Can't launch ikvm via JAVA" It is due to a JAVA certificate that expired, renewed certificate.2. LCMC information will disappear and fan function abnormal after reboot." It is due to wishbone's strange behavior, and causes an CPLD internal flash program to not able to end normally. Added a dummy command to CPLD to work around it. So EEPROM -VPD programming could be flashed to CPLD wishbone.3. "NIC sensor temp drop" issue is fixed.4. Fixed "False PSU status in WEBgui when power reset".

Release Notes from Previous Release(s)

00.01.04 (12/17/2021)

1. Added RTX A4000, A100 80GB, A100 40GB SXM4 and A100 80GB SXM4 to support list.
2. Supported new IPMI OEM command for OTP features.
3. Supported new IPMI OEM command for CPLD validation.
4. Supported CPLD firmware update with JED file (with 5320 ROT table in UFM) for the motherboard, midplane, and backplane.
5. Extended IPMI OEM command to get the FW version and the RollbackID of the CPLD.
6. Extended IPMI OEM raw command to support CPLDROT table.
7. Extended IPMI OEM raw command to support CPLD FW signature validation.
8. Displayed version of MB CPLD FW file before updating.
9. Supported MB CPLD FW update with signed JED file.
10. Supported MEL for midplane and backplane CPLD firmware update.
11. Supported AIC type sensors in fan control mechanism.
12. Added onboard M.2/U.2 drive Redfish URI.
13. Fixed wrong location of memory sensor reading.
14. Fixed FW ECO failing at BMC Gold image validation.
15. Fixed power supplies sensor incorrect readings.
16. Changed BMC SEL event for AMD CPU thermal sensor; instead of generating CPU throttling event, generate over threshold event if the nine consecutive temperature readings from CPU Tctl are equal to or higher than Tctl_max.
17. Adjusted the thresholds for MEM and VDDCR voltage sensor.
18. Fixed MCX512A-ACAT false overheating SEL NIC AOC temperature value incorrect when DC is on for the first time.
19. Disallowed user to enter 65 characters as Authentication Key and Encryption Key when setting Alerts with SNMPv3 protocol.
20. Fixed GPU power sensor mismatch by adding support for NVidia power consumption reading as an SDR sensor.
21. Fixed the BMC reporting incorrect DIMM.
22. Fixed the BMC returning error on PSU information inquiry when only one PSU is connected to the passive board of H12SSG.
23. Fixed the power consumption displaying 0 for the upper and lower bounds.
24. Fixed Redfish SATC automation test failure.
25. Enabled IPMI FAN heavy IO control.
26. Fixed the BMC firmware upgrade to take less than ten minutes to meet PAS requirement
27. Fixed incorrect PSU power consumption and status.
28. Fixed system UI showing critical icon by filtering the correct PSU and GPU sensor number.
29. Hid misleading LAN MAC address.
30. Enabled NCSI initialization when DC ON.
31. Set fan duty to 20% when the node is DC off in the system.
32. Fixed the fan information in WebGUI when the fan is removed.
33. Fixed the password length to match help info.
34. Enabled permanent display of the BMC static IPv4 address.
35. Added checking condition to disable the user to set Authentication Key and Encryption Key with space or special characters.
36. Fixed the front panel red LED staying on after the system overheats.
37. Fixed the GPU power consumption getting the wrong SEL.

38. Fixed the failure to update the BIOS through Redfish and SUM.

00.00.29 (9/17/2021)

1. Moved BIOS image checking after DC powers on.
2. Added support for RTX A5000.
3. Revised sdrmake.sh to generate SDRBlock files to OEM location.
4. Fixed loss of dynamic sensor when doing firmware update without keeping SDR configuration.
5. Set performance PCH code to reset to recovery BMC's power control and enabled motherboard to be powered.
6. Set FRU block file on Twin Pro type device to be used.
7. Fixed missing sensor readings for the DCMI.
8. Fixed bug with BMC IP 0.0.0.0.
9. Fixed problems of PSU WebGUI showing error while system is booting up with AC ON and BMC reporting NA before detecting PSU.
10. Fixed problem of system UI showing critical icon due to PSU power consumption read error.
11. Fixed problem of H12SSG-AN6 H12SSH-AN6-NC24B WebGUI multi-node showing as empty when system config ID is set to 0x03, and set SSG multi-node default UI as 2 node.
12. Fixed compatibility of multi-node layout with new and old LCMC CPLD firmware showing 2 nodes with top/bottom layout.
13. Fixed issue of CM USI feedback cut-in ECO25597/ECO25502 H12SSG-AN6-NC24B function test finding COM port test.
14. Implemented workaround for Dump CPLD DBoot Image for H12SSW-AN6-NC24B motherboard CPLD.
15. Fixed inability to enable RADIUS when setting server address with IPv6 for NVidia Web.
16. Added multi-node layout for config 3 with MidPlane CPLD 0104.
17. Fixed problem of Sensor Table data corruption causing partial/all sensor readings to freeze or show as NA.
18. Fixed problem of AOC NIC sensor dropping during DC ON/OFF due to I2C MUX error and PLDM protocol being interrupted.
19. Fixed failure of NVMe status polling task to stop in time when motherboard powers off so that false event is generated.
20. Set SSDP to disabled as the default setting.
21. Removed PCH release related code in DC ON process.
22. Corrected PSU power consumption and status.
23. Corrected the inlet temperature offset.

00.00.22 (7/20/2021)

1. Added single firmware image to support both 2600-A3 chips with Big-endian key mode and A1 chips with Little-endian key mode.
2. Added new IPMI command to get AST2600 chip revision.
3. Fixed loss of GPU Temp Sensor.
4. Fixed problem of BBP error message occurring during ON/OFF.
5. Fixed problem of CPU overheating at 35C inlet temperature while CPU performance boost is disabling at C1 OEM SKU, failure of system FAN to reach full speed while system starts up with only 3 fans, failure of fan speed to rise while CPU is overheated, problem of FAN dropping to 50% duty when CPU temperature hits critical threshold, and missing CPU throttling control (program CPLD GPO0 to assert/de-assert throttling signal P0_PROCHOT#).
6. Fixed problem of system showing as "Unhealthy" when temperature polling of NIC is not supported.
7. Adjusted VBAT critical and fixed missing threshold from 2.7~2.5 to 2.6~2.4.

8. Enabled dump of OTP data via RedFish command.
9. Improved midplane CPLD update design, added verification of midplane CPLD ID and hardware reversion before update, and added Redfish command to get midplane CPLD version.
10. Fixed problem of PSU DMI Info dropping during AC ON/OFF.
11. Fixed problem of H12SSG-AN6-NC24B showing a message in event log when running stress test.
12. Fixed issue with FW0.0.17 while doing provision.
13. Corrected CPLD version for midplane CPLD received by the register offset.
14. Set CPLD ROT table and signature to write to CFM for midplane CPLD.
15. Corrected power reading on WebGUI.
16. Corrected display of midplane CPLD version.
17. Fixed issue with IPMI WebGUI compatibility with Firefox browser password management.
18. Fixed failure of WebGUI fan to show as critical before sensor reading while motherboard boots up.
19. Fixed problem of M.2 temperature becoming NA during sensor monitoring.
20. Fixed problem of GPU temperature sensor dropping for high cycle DC ON/OFF test, improved GPU discovery with proper delay and retry when encountering error, and added log when new added code branch is entered and corrects error.
21. Protected GPU Mux switch module to improve GPU discovery.
22. Set GPU discovery to wait until GPU firmware boot completes.
23. Fixed issue with flashing IPMI with A3 chip.

00.00.15 (6/2/2021)

Initial Release