IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSW-iNR/NTR		
Release Version	01.01.04		
Release Date	03/21/2022		
Previous Version	1.00.41		
Update Category	Critical		
Dependencies	N/A		
	ECO #26522		
Important Notes	BMC_H12AST2500-ROT-2201MS_20220321_01.01.04sp.bin		
	Please update IPMI with attached Flash Utility in package.		
Enhancements	N/A		
New features	N/A		
Fixes	1. OS Ip will be lost after running 2xx OOB test case when using AOC-URG4N4-i4XTS card for onboard LAN 2. Anonymous" user will disappear after filtering any account type 3. Error message format isn't the same when upload invalid FW file 4. The tips still appear when unchecking SNMP check box when add user account 5. Virtual Media couldn't mount ima file on Java iKVM 6. Error message doesn't match actual situation when fail to mount iso file 7. AOC sensor temp/status is not meet spec 8. AOC-SLG3-2H8M2 (OOB mode is i2c) information can't display on BMC GUI 9. BMC Network AOC Location/Sensor name information is abnormal 10. BMC hasn't AOC_PMCX TEMP sensor for AOC-SLG4-2E2T 11. redfish automation tool check is failed 12. SMCIPMITool fail to set the gateway to 0.0.0.0		

1.00.41 (10/22/2021)

- 1. IPMI Sensor mismatch during running share LAN Cburn ONOFF
- 2. Add FPGA driver to support Xilinx FPGA card (U-series)

1.00.36 (06/16/2021)

Fixed Redfish SimpleUpdate API failed for BIOS firmware update.

1.00.33(02/23/2021)

- 1. Added support GPU Nvidia A40
- 2. Added support get HBM temp for AMD GPU MI100 A2
- 3. Fixed IPMI will send "[BIOS] SPI Channel attack is prevented" during DC stress
- 4. Alert LED will keep blinking when power state was recovered

1.00.25 (10/29/2020)

- 1. Fixes the BMC FW 1.0.6 unique password cannot be recovered by command 0x30 0x40
- 2. [114014] [New Web UI] The format in Inventory page is not matched with latest SPEC
- 3. [New Web UI] There are some items in some pages not be translate to Japanese and Simplified Chinese
- 4. The format in Inventory page is not matched with latest SPEC
- 5. [SUM-UEFI_100b200623] SUT will not power on automatically after "-c BiosRotManage --action Update Golden --reboot" process completed.
- 6. [116732] [ECO]It takes long time to trigger Alert LED when IPMI detect power failure
- 7. Cannot update BIOS through BMC Web UI.
- 8. Cannot use remote console function.
- 9. IPMI ECO automation test failed.
- 10. NVMe SSD eject function failed in IPMI WebGUI
- 11. Got the fail results via SMSTC of the H12SSW-NTR
- 12. [113611] [New Web UI] Sensor status shows Critical but System status and sensor reading are normal
- 13. [113613] [ROT] BIOS recovery event log display twice in SEL on IPMI v1.0.8
- 14. [113790] IPMI ECO automation test failed.
- 15. [113393] [New Web UI] Login page will show "Browser not support" even using Chrome already in sometimes
- 16. [112993] [New Web UI] TDP Watts is 0 in Component Info CPU page
- 17. [116699] [SMCIPMITool_2.24.0_b200904] ukvm fail on some RoT projects. (ex: H12SSW-NTR) but Non-RoT ones pass.
- 18. [105659] [DVT]NVMe ejected randomly during IPMI on/off test
- 19. [116224] [IPMI:1.00.17] IPMI execution failed in run IPMI ECO Automation.
- 20. [109736] [SUM] got the fail results via SMSTC of the H12SSW-NTR
- 21. [105730] SATC redfish automation standard mode test fail
- 22. [118852] Set up IPMI login password with "\" character and user cannot login
- 23. [117484] Alert LED will keep blinking when power state was recovered
- 24. [116737] [ECO]It takes long time to detect FAN failure when FAN connector was disconnected.
- 25. MBD CPLD version not present in IPMI web GUI dashboard

First release. ı	16/	′1 <i>∩</i> /	2020