BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12QCH+-P (1.01)
Release Version	1.1
Release Date	01/06/2022
Build Date	01/06/2022
Previous Version	1.0c
Updated Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	 Updated the BIOS version to 1.1. Updated Cooper Lake A1 stepping CPU microcode MBF5065B_07002402 for INTEL-SA-00532 Security Advisory to address CVE-2021-0127(5.6, Medium). Updated SPS version 4.4.4.048. Checked SPS functions like Node management. Updated Intel BKC 2021.2 IPU for INTEL-SA-00562 Security Advisory to address CVE-2021-0158(8.2, High). Updated BIOSACM version 1.3.2 and SINITACM version 1.3.2 for INTEL-TA-00527 Security Advisory to address CVE-2021- 0099(7.8, High), CVE-2021-0107(7.2, High), CVE-2021-0111(7.2, High), CVE-2021-0114(8.2, High), CVE-2021-0115(8.2, High),
	CVE-2021-0116(8.2, High), CVE-2021-0117(8.2, High), CVE-

	2021-0118(8.2, High), CVE-2021-0125(6.7, Medium), CVE-2021-
	0124(6.3 <i>,</i> Medium).
	7. Updated VROC sSATA/SATA driver version 7.6.0.1012.
	8. Updated PMem UEFI version 2.0.0.3878.
	9. Added flag [Preserve BIOS Boot Options Configuration]
	controlled by BMC/SUM.
	10. Redefined Enhanced PPR for AMT2.0 update.
	11. Changed string "VMX" to "Intel Virtualization Technology".
	12. Added support for system configuration F & G.
New features	None
	1. Removed 1G option from MMCFG base to avoid system hang.
	2. Fixed the SMBIOS event log ERROR CODE that is not displaying correctly under BIOS menu issue (EFI error type).
Fixes	Fixed the setup item "Lockdown Mode", which is always grayed-out.
	 Fixed SpeedStep (P-States) which changes settings when its default setting is set to Disable and load BIOS defaults in Setup.

Release Notes from Previous Release(s)

1.0c (12/01/2021)

- 1. Updated BIOS to version 1.0c.
- 2. Updated SPS version 4.4.4.035.
- 3. Updated 5.19_CedarIslandCrb_0ACMT_016 Intel BKC WW20 PLR2.
- 4. Updated BIOSACM version 1.0.A and SINITACM version 1.0.A.
- 5. Updated VROC sSATA/SATA driver version 7.5.0.1152.
- 6. Updated PMem UEFI version 2.0.0.3866 and PMem FW version 2.2.0.1553.
- 7. Added code to stop AFU support.
- 8. Enhanced Smc Dcpmm feature.
- 9. Extended DIMM memory serial number information. (Samsung, Micron, Hynix)
- 10. Removed Intel LAN memory 4G limit if boot mode is not legacy.
- 11. Set all OPROM control items to Legacy when boot mode set to Dual.
- 12. Set PCH PCI-E ASPM to disabled if CPU PCI-E global ASPM is disabled.
- 13. Updated CPLD Signature table 101.
- 14. Changed "SMCI PMem Formset" to "SMCI PMem Configuration".
- 15. Changed "Hard Drive Security Frozen" default setting to disabled.
- 16. Added support for recovering boot status after flashing ROM through BMC/CPLD.
- 17. Added support for Supermicro Update Manager (SUM) upload/delete HTTPS TLS certificate.
- 18. Changed BIOS to prevent "Power Performance Tuning" being selected, when loading the BIOS default.
- 19. Now supports EUI-48 Locally Administered MAC Address.
- 20. Updated SmcOOB module to 1.01.24 to support SUM clean SMBIOS Event log through BiosCfg header flag.
- 21. Disabled EFI iSCSI support.
- 22. Revised Me version strings, removed the "Manufacturer ID" string.
- 23. Fixed the HDD security menu, it will not show when connecting more than 6 HDDs on the system.
- 24. Fixed an issue where the IPV6 address still appears even if IPV6 is disabled in the IPMI GUI.
- 25. Fixed system freeze with Micron 2300 256GB NVMe installed.
- 26. Fixed an issue where the memory device in IPMI does not match the BIOS setup when some memory DIMMs are mapped out.
- 27. Fixed UEFI OS boot option name that shows incorrectly in BIOS setup.

28. Fixed to prevent erasure a TCG device without an installed password. Fixed wrong FW version and vendor name in Trusted computing page.

29. Updated SMCOOB to keep the NVRAM variables that should be kept (SGX vars, KMS Vars, ...) when executing "sum.exe -c LoadDefaultBiosCfg".