

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|--|
| Product Name | X11SCL-LN4F |
| Release Version | 1.8 |
| Release Date | 08/01/2022 |
| Build Date | 08/01/2022 |
| Previous Version | 1.6 |
| Update Category | Recommended |
| Dependencies | None |
| Important Notes | None |
| Enhancements | <ol style="list-style-type: none">1. Enabled token "IPMI_FORCE_BOOT_UEFI_SHELL" to support shell by IPMI, changed boot order command.2. Supports IPMI UEFI PXE boot to all LAN port feature.3. Updated Microcode M22906EA_000000F0(U-0 Stepping) and M22906ED_000000F0(R-0 Stepping) for INTEL-TA-00615 to address CVE-2022-21166(5.5 High), CVE-2022-21123(6.1 High), CVE-2022-21127(5.6 High), for INTEL-TA-00617 to address CVE-2022-21151(5.3 High), for INTEL-TA-00614 to address CVE-2022-0005(4.9 High) |

| | |
|--------------|--|
| | <ol style="list-style-type: none"> 4. Updated Intel SINIT ACM to 1.10.1. For INTEL-TA-00601 to address CVE-2021-33123 (8.2 High), CVE-2021-33124 (7.5 High) security issues. 5. Updated SPS FW to SPS_E3_05.01.04.600.0 for IPU 2022.2. 6. Changed BIOS version to 1.8. 7. Updated UEFINetworkStack to label 28 and added patch for AMI SA-50110 security issue. |
| New features | N/A |
| Fixes | <ol style="list-style-type: none"> 1. SUM cannot get the item "Software Guard Extensions (SGX)" from the BIOS configuration via <code>sum -c getcurrentbioscfg</code> command. 2. Fixed automation test case "Check Https Boot" fail. |

1.6 (8/6/2021)

1. Changed the BIOS version to 1.6.
2. Updated Microcode M22906EA_000000EA (U-0 Stepping) for INTEL-SA-00464 Security Advisory to address CVE-2020-24512 (2.8, Low) security issue.
3. Updated SPS FW to SPS_E3_05.01.04.303 for INTEL-TA-00459 Security Advisory to address CVE-2020-24509 (6.7, Medium) IPU 2021.1.
4. Updated Intel BIOS ACM and SINIT ACM to 1.8.0 for INTEL-TA-00463 to address CVE-2020-12357 (7.5, High), CVE-2020-8670 (7.5, High) and CVE-2020-12360 (5.6, Medium) security issues.
5. Copied the BIOS binary and renamed it to meet the unique name format.

N/A

6. Fixed SUM test 220 fail due to "PCI AER Support" and "Memory Corrected Error Enabling" setting not preserved after flashing BIOS.

1.5 (10/05/2020)

1. Changed the BIOS version to 1.5.
2. Updated microcodes M22906EA_000000DE (U-0 Stepping), M02906EB_000000DD_000000DE (B-0 Stepping), M22906EC_000000DE (P-0 Stepping), and M22906ED_000000DE (R-0 Stepping) for Intel IPU 2020.2.
3. Updated SPS firmware to SPS_E3_05.01.04.208.0 for INTEL-TA-00391 Security Advisory to address CVE-2020-8744 (7.2, High) and CVE-2020-8755 (4.6, Medium) security issues.
4. Updated Intel IPU 2020.2 RC 7.0.58.47 for Mehlow Refresh Server Platform Service Version.
5. Removed the FWSTS SMBIOS table.
6. Reduced Rowhammer susceptibility for AMI-SA50084 DDR4 Rowhammer vulnerability to address CVE-2020-10255 (9.0, high) security issue.
7. Patched inability of system to boot via onboard LAN2 after IPMI forces PXE boot when there is an OS behind LSI-3108 RAID card.
8. Added inband flash status event log to IPMI MEL.
9. Added Hotkey Message Enable/Disable function.
10. Enhanced SMCI HDD Security feature.
11. Changed SPI TPM Clock Frequency to 17MHz for TPM detection.
12. Fixed problem of BIOS setup menu showing "Unknown" when plugging in the InnoDisk memory and boot up into BIOS setup menu.

1.4 (5/28/2020)

1. Changed the BIOS version to 1.4.
2. Implemented IPU 2020.1 update to SPS firmware to SPS_E3_05.01.04.113.0.
3. Enhanced the OEM FID feature to support UUID.
4. Updated Intel RSTe RAID Option ROM/UEFI Driver to 6.3.0.1005.
5. Added SMCI HDD Security feature.
6. Updated microcodes M22906EA_000000D6 (U-0 Stepping), M02906EB_000000D6 (B-0 Stepping), M22906EC_000000D6 (P-0 Stepping), and M22906ED_000000D6 (R-0 Stepping) for INTEL-SA-00320

Security Advisory to address CVE-2020-0543 (6.5, High) security issue, and microcodes M22906EA_000000D6 (U-0 Stepping), M02906EB_000000D6 (B-0 Stepping), M22906EC_000000D6 (P-0 Stepping), and M22906ED_000000D6 (R-0 Stepping) for INTEL-SA-00329 Security Advisory to address CVE-2020-0548 (2.8, Low) and CVE-2020-0549 (6.5, Medium) security issues.

7. Set the OverclockingLock flag to enabled by default for SGX test.
8. Added support for InnoDisk memory.
9. Fixed inability to change the serial port IO resource.
10. Fixed failure of Secure Erase password and problem of BIOS returning "EFI_Device_Error" with SED: Seagate ST1000NX0353.

1.3 (2/21/2020)

1. Added solution for problem of systems with LPDDR3 2133 MT/s DRAMs failing during boot.
2. Corrected the "DeepSx Power Policies" item string.
3. Updated RC to Mehlow Refresh PV version 7.0.58.44.
4. Displayed the "SGX Launch Control Policy" items in the BIOS setup menu.
5. Added SMC HDD Security feature.
6. Updated Microcodes M22906EA_000000D2 (U-0 Stepping), M02906EB_000000D2 (B-0 Stepping), M22906EC_000000D2 (P-0 Stepping), and M22906ED_000000D2 (R-0 Stepping) for INTEL-SA-00320 Security Advisory to address CVE-2020-0543 (6.5, High) security issue and for INTEL-SA-00329 Security Advisory to address CVE-2020-0548 (2.8, Low) and CVE-2020-0549 (6.5, Medium) security issue.
7. Updated flag for skipping password prompt window.
8. Updated BiosAcm to 1.7.1 (20191213) and SinitAcm to 1.7.8 (20191220) for INTEL-SA-00240 to address CVE-2019-0151 (7.5, High) and CVE-2019-0152 (8.2, High), for INTEL-SA-00220 to address CVE-2018-0123 (8.2, High) and CVE-2019-0124 (8.2, High), and INTEL-SA-00164 to address CVE-2019-0184 (6.0, Medium).
9. Fixed inability of ME to enter recovery mode.
10. Fixed inability of BIOS to load default when plugging in M.2.
11. Added support for erasing NVMe Opal device (like Samsung 970 EVO model MZ-V7E250) without setting admin password.

1.2 (11/22/2019)

1. Changed BIOS version to 1.2.
2. Disabled the MCTP for buggy BMC workaround.
3. Updated Microcode M22906EA_000000CA (U-0 Stepping), M02906EB_000000CA (B-0 Stepping), and M22906EC_000000CA (P-0 Stepping) for INTEL-SA-00219 Security Advisory to address CVE-2019-0117 (6.0, Medium) security issue and for INTEL-SA-00220 Security Advisory to address CVE-2019-0123 (8.2, High) security issue.
4. Updated Microcode M22906ED_000000CA (R-0 Stepping) for INTEL-SA-00219 Security Advisory to address CVE-2019-0117 (6.0, Medium) security issue, Microcode M22906ED_000000CA (R-0 Stepping) for INTEL-SA-00220 Security Advisory to address CVE-2019-0123 (8.2, High) security issue, and Microcode M22906ED_000000CA (R-0 Stepping) for INTEL-SA-00270 Security Advisory to address CVE-2019-11135 (6.5, Medium) security issue.
5. Updated SPS firmware to SPS_E3_05.01.03.094.0.
6. Updated the Intel PMC firmware to 300.2.11.1022.
7. Updated the AMI TSE to 2.20.1276.

8. Updated RC to Mehlow Refresh PV version 7.0.58.43 for INTEL-SA-00260 Security Advisory to address CVE-2019-0154 (6.5, Medium) security issue.
9. Updated SINIT ACM to 1.7.4 for INTEL-SA-00240 to address CVE-2019-0151 (7.5 High) and CVE-2019-0152 (8.2 High), INTEL-SA-00220 to address CVE-2018-0123 (8.2, High) and CVE-2019-0124 (8.2, High), and INTEL-SA-00164 to address CVE-2019-0184 (6.0, Medium).
10. Updated NVRAM NVMe HddSecurity SmmConfidentialMemModule and TcgStorageSecurity to INTEL-SA-00254 request version for INTEL-SA-00254 Security Advisory to address CVE-2019-0185 (6.0, Medium) security issue.
11. Fixed problem of CECC being recorded in event log when METW is "60".

1.1 (8/28/2019)

1. Changed the BIOS version to 1.1.
2. Set memory uncorrectable error to always be recorded, regardless of METW and MECI.
3. Updated SPS firmware to SPS_E3_05.01.03.078.0.
4. Added "SATA Frozen" function.
5. Updated SMC OOB module to 1.01.08, added Redfish/SUM Secure Boot feature, and updated OOB for secure boot and reserve Key.
6. Updated RC to Mehlow Refresh PV version 7.0.58.42.
7. Implemented dynamic change for Secure Boot Mode default value.
8. Fixed inability of BIOS to get SMBIOS type 39 power supply FRU data.
9. Updated Coffee Lake-S R-0 stepping CPU microcode M22906ED_000000BE and Coffee Lake-S P-0 stepping CPU microcode M22906EC_000000BE.
10. Displayed setup item "BME DMA Mitigation" on the Advanced -> PCIe/PCI/PnP Configuration page.
11. Fixed problem of SATA Configuration page showing 1TB for 8TB 4KN HDDs.
12. Fixed problem of key details showing "Security Violation" after loading Factory secure boot keys.
13. Fixed problem of two boot devices occurring in the boot order when installing UEFI CentOS.
14. Fixed failure of OPROM control item if CSM is disabled.
15. Fixed inability of system to find any network adapters and problem of the installation with vSphere aborting.
16. Fixed inability to enable TPM in the BIOS setup menu when plugging in TPM device and then disabling it.
17. Fixed problem of some items being adjusted when user adjusts dual boot order in BIOS setup.
18. Fixed inability to identify duplicated NVMe boot option with more than one of the same NVMe drives on an add-on card.

1.0b (5/17/2019)

1. Updated BIOS version to 1.0b.
2. Updated RC to version 7.0.58.41.
3. Updated Coffee Lake-S R-0 stepping CPU microcode M22906ED_000000B0.
4. Updated MCU 906EA-U0 + 906EB-B0 + 906EC-P0) for INTEL-SA-00233 Security Advisory to address CVE-2018-12126, CVE-2018-12127, and CVE-2018-12130.
5. Update SPS 5.1.03.62 for INTEL-SA-00213 Security Advisory to address CVE-2019-0089, CVE-2019-0090, CVE-2019-0086, CVE-2019-0091, CVE-2019-0092, CVE-2019-0093, CVE-2019-0094, CVE-2019-0096, CVE-2019-0097, CVE-2019-0098, and CVE-2019-0099.

6. Update SPS 5.1.03.62 for INTEL-SA-00213 Security Advisory to address CVE-2019-0089, CVE-2019-0090, CVE-2019-0086, CVE-2019-0091, CVE-2019-0092, CVE-2019-0093, CVE-2019-0094, CVE-2019-0096, CVE-2019-0097, CVE-2019-0098, and CVE-2019-0099.
7. Updated Intel RSTe RAID Option ROM/UEFI Driver to 6.1.0.1017.
8. Updated USB and Fastboot module.
9. Enhanced the solution for the error/warning message from dmidecode after a modification by AMIDE.
10. Exposed the CPU's PL1 and PL2 items of Advanced -> CPU Configuration page in the BIOS setup menu.
11. Renamed "AC Loss Policy Depend on" back to "Restore on AC Power Loss".
12. Updated to avoid inability to flash OA License Key randomly.
13. Added Driver Health setup item.
14. Added driver health warning message.
15. Added OEM strings to 50 bytes in Type 11.
16. Updated IPv4 and IPv6 setup items string.
17. Updated BIOS Setup Menu for the item "Always Turbo Mode" in Advanced/CPU Configuration page.
18. Added code for Consistent Device Name support.
19. Added support for Linux built-in utility efibootmgr.
20. Set default setting Power Limit 2 to 150W when 8 Core CPU is used in the system.
21. Set OptionRom and boot mode select to EFI while CSM is disabled.
22. Changed UEFI Lan Boot option name format for SUM requirement.
23. Added RFC3021 solution for the network stack (/32 subnet mask support).
24. Exposed the setup item "BME DMA Mitigation" in the Advanced -> PCIe/PCI/PnP Configuration page.
25. Fixed issue of DIMM location to show "i§No DIMM infoj" in Event Logs when ECC error occurs.
26. Fixed issue of DIMM location to always show "DIMMA1" in BIOS Event log when ECC error occurs.
27. Fixed issue of ""[1;31;40m" being shown on POST screen when EFI driver is "unhealthy".
28. Fixed issue of BMC VGA status showing Enabled in SMBIOS Type 41 when JPG1 is disabled (In 2-3).
29. Fixed issue of onboard video having an output when JPG1 is disabled.
30. Fixed problem of hot-plug being registered when the PCH root port bridge is without a PCI-E device.
31. Updated "Restore Optimized Defaults" string for Mehlow Server template.
32. Modified UEFI network description as IPv4/IPv6 to follow Industry Standard.
33. Added workaround for BIOS flash failure with 156 bytes PubKey (Error: "Secure Flash Rom Verify Fail").
34. Fixed problem of the system hanging in CP: 0xF4 when the system recovery occurs in BIOS with TPM module.
35. Fixed problem of the value of Power Limit 2 displaying as 0 in setup menu when setup menu is set to 0 (AUTO).
36. Fixed issue of system may or may not hanging up when LAN1 is disabled.
37. Fixed DIMM location of ECC error to show "NO DIMM INFO" in Event log when Multi-Bit ECC error occurs.

1.0a (2/26/2019)

1. Updated BIOS revision to 1.0a.
2. Updated Intel Reference Code to version 7.0.51.40.
3. Updated CPU MCU (906EA, U0 + 906EB, B0 + 906EC, P0).
4. Hid LAN OPROM Control items when LAN#1 OPROM is set to iSCSI.

5. Added Early Video messages when BIOS is in recovery mode.
6. Added "ACPI T-States" setup item.
7. Displayed "AERON" and "MCEON" strings during POST when "PCI AER Support" or "Memory Corrected Error" is enabled.
8. Hide "ECC Support" item.
9. Set the default of "Memory Corrected Error Enabling" to disabled.
10. Updated the Intel BIOS ACM version to 1.5.0 and SINIT ACM to 1.6.0.
11. Added "SMC SMBIOS Measurement" feature for PCR#1 measurement and enabled "Measure_Smbios_Tables".
12. Updated RAID option ROM and UEFI driver to 5.5.1028.
13. Added "MCEON" and "AERON" POST strings for SOL console when items are enabled.
14. Enhanced JPG1 function for running SUM with JPG1 2-3.
15. Added support for RFC4122 UUID format feature so that RFC4122 encoding from build time is produced by IPMICFG 1.29 tool or newer version.
16. Added "SATA Frozen" function.
17. Added support for Linux built-in utility efibootmgr.
18. Hid "Always Turbo Mode" when "Turbo Mode" setting is set to Disable in Advanced/CPU Configuration page.
19. Updated IPv4 and IPv5 setup item strings.
20. Added OEM strings to 50 bytes in Type 11.
21. Added Disabled option for "Onboard Video Option ROM" setup item.
22. Added "Driver Health" setup item.
23. Added Driver Health warning message.
24. Renamed "AC Loss Policy Depend on" to "Restore on AC Power Loss".
25. Enhanced the solution for the error/warning message from dmidecode after AMIDE modification.
26. Updated SMBIOS Type 9 for AOC Sensor Reading.
27. Fixed inability to Boot Option of UEFI Application Boot Priorities to load default via Afu tool with command "/N".
28. Changed the "SATA Interrupt Selection" default value to MSI.
29. Fixed problem of Chassis Intrusion status in BMC clearing every time system boots.
30. Fixed issue of serial port UID order to follow COM port order after BIOS update.
31. Fixed issue of PCR#1 value to be changed during Legacy boot with TPM 2.0 when Measure_Smbios_tables is disabled.
32. Fixed problem of the system having an exception while entering BIOS Setup with NVMe M2*1 + SATA M2*1.
33. Fixed problem of InBand receiving incorrect OEM FID size.
34. Fixed problem of system hanging in CP during system recovery BIOS with TPM module.
35. Updated "Restore Optimized Defaults" string for Mehlow Server template.
36. Modified UEFI network description to IPv4/IPv6 to follow Industry Standard.
37. Removed processor version "Type" string for Mehlow Server template.
38. Fixed issue of onboard video output displaying screen on DXE stage when JPG1 is disabled.
39. Updated "Redirection After BIOS POST" string for Mehlow Server template.
40. Fixed problem of BMC VGA status being enabled in SMBIOS Type 41 when JPG1 is disabled (In 2-3).
41. Fixed lack of onboard VGA information in Type 40.