

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13DSH
Release Version	01.00.17
Build Date	03/29/2023
Previous Version	01.00.14
Update Category	Critical
Dependencies	BIOS:1.4 (BIOS_H13DSH-1C84_20230419_1.4_STDsp)
Important Notes	BMC image: BMC_H13AST2600-ROT-1401MS_20230329_01.00.17_STDsp.bin BMC image and flash utility package: BMC_H13AST2600-ROT-1401MS_20230329_01.00.17_STDsp.zip Please update with BIOS:1.4 with CPLD:F5.0F.1C and contact our technical support for any inquiries about CPLD.
Enhancements	1. Added support for Remote Attestation.
New features	N/A
Fixes	1. Fixed the problem of no SSDP in the Help tips. 2. Fixed the problem of Syslog packet not following the RFC3164 format. 3. Added the capabilities of ng Blink or Insert HDD buttons when the system was in lockdown mode. 4. Modified the tune I3C clock parameters to be compatible with more DIMM models. 5. –Fixed the problem of no error message appearing when the text entered in the SNMPv2 Name field was incorrect.

Release Notes from Previous Release(s)

01.00.14 (2023/02/10)

[Enhancement]

Improved the MB cpId jtag port to be locked.

[Fixes]

- 1. Fixed the problem of failing to read the correct power status when an H13 system was not installed with an AMD CPU.*
- 2. Fixed the issue in which MELL Log msg was incorrect when only the Dynamic option was enabled.*

01.00.12 (2023/01/17)

[Enhancement]

- 1. Improved the problem of the SMBUS reading and writing the NIC card.*
- 2. Added short-term solution to improve NVMe eject/insert glitches.*

[Fixes]

Fixed the following issues:

- 1. The PSU failure LED is ON when CPU temp reaching sensor threshold. The PSU failure LED is blinking when removing PSU module. The PSU failure LED is blinking when removing FAN module.*
- 2. Missing SEL logs "[PWR-0000] PS Status, Power Supply Installed - Assertion" after system power on with IPMI 01.00.08*
- 3. IPMI Web - help page link confirm and Web - help page link confirm.*
- 4. Deploy OS test fail (error message:Failed to mount iso on 10.184.21.36) on the H13SSL-NT and executed the diagnose system under SSM v5.4.*
- 5. MCX75510AAS-HEAT ands MCX653105A-ECAT not detected NAOC info on BMC Web.*
- 6. Call home trigger item (temp:Local Administrator Setting) no match SSM design on the H13SSL-NT.*
- 7. There are duplicate BMC events when triggering CPU temp sensor.*
- 8. Enabled the "Task Message" when BIOS firmware verify and updated completed.*
- 9. Failed in IPMIECO TC0002, TC0019, TC2015 and error message "Cannot establish SSL connection."*
- 10. When DIMM is inserted into position G1~F1, the incorrect DIMM name is displayed.*

01.00.06 (2022/11/15)

Initial Release