

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SST-G/GC
Release Version	01.01.08
Release Date	10/06/2023
Previous Version	01.01.03
Update Category	Recommend
Dependencies	N/A
Important Notes	N/A
Enhancements	1. Update AMD RAS crash dump to ADDC 1.8 2. PSU FAN page synchronization with PSU page
New features	1. Support IPv6 enhancement spec
Fixes	1. Fix Current owner index is wrong after RA provision 2. MEL-0135 displays more than 3 times 3. BMC cannot obtain IP 4. [163528] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM/ [163845] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM 5. [163529] ECO — 21603 — 01.01.07(09/22/2023) — [MEL] — No related MEL when disable TSIG Authentication 6. [162844] STD -- 21603 -- 01.01.05 (2023/09/08) -- WEB -- MEL is incorrect after do ikvm reset 7. [162823] ECO -- 21603 -- 01.01.05 -- Remote Console Preview current interface button enabled

	8. [160509] ECO — 21603 — 01.01.01(07/21/2023) — [MEL] — should non-set IPv4 DNS Server IP related MEL be shown when setup Hostname or not 9. [156498] ECO -- 21603 -- 01.00.18 -- [MEL] should non-set IPv4 DNS Server IP related MEL be shown when setup IPv6 DNS Server IP or not 10. [162843] [IPMI 1.01.05 ECO] IPMI display "PCIE PERR error" when inject memory UECC/ [162842] [IPMI 1.01.05 ECO] IPMI display incorrect location when inject memory CECC/ [151917] [AMD RAS][CH6] No show OS error log when execute "GMI3/xGMI3 Error Injection" 11. Fix OTP flush error and should stop provision 12. [159725] [RoT] Update CPLD Golden image event log timestamp is incorrect 13. [160511] ECO -- 21603 -- 01.01.01(07/21/2023) -- Could not mount ISO via SMCIPMITool when Virtual Media does not mount any ISO or floppy
01.01.03 (08/23/2023) 1. Redfish support new OEM FixedBootOrder API to replace BootOrder for change bios boot option 2. [299 Phase 1] Disable IPMI Lan Port Interface 3. [299 Phase 1] HTML5 Console as default 4. [299 Phase 1] Dual mode for network setting as default 5. [299][MultVM] Virtual media support 3 CD/FLOPPY image mounting 6. [Enhancement] Modify Dedicated Link options: Add 1G Full and remove 10M Half/Full 7. Fix PCIe dump issue with AMD RAS crash dump 8. [160511] ECO -- 21603 -- 01.01.01(07/21/2023) -- Could not mount ISO via SMCIPMITool when Virtual Media does not mount any ISO or floppy 9. [160497] ECO — 21603 — 01.01.01(07/21/2023) — [GUI] — Deditcated Link speed has 10M speed 10. Provision failed 11. [155635] [Bergamo][SD5_5.17.0_b1062] Redfish credential bootstrapping test fail flash BIOS need key-in user and password on H13SST 12. [155625] [Bergamo][SSM_5.4.0_build.1214]No CPU Speed in SSM System Information on H13SST 13. [156576] ECO -- 21603 -- 01.00.18 -- [MEL] generated MEL not quite match when add SNMPv2 (based on MEL SPEC v1.03) 14. [157556] [IPMI ECO 01.00.19]Redfish automation failure. [159180] [IPMI ECO 1.00.20]Redfish automation tool check is fail. [159406] [BIOS 1.5][IPMI 01.00.20]Redfish automation Failed. [159513] Redfish automation test failed. 15. [156537] ECO -- 21603 -- 01.00.18 -- Fail to add valid Prefix length128 for IPv6 Static Route List 01.00.17 (03/29/2023) 1. Expand IPMI OEM 80 commands.	

2. (1) Enhance Power Event Handler/ (2) Add PWROK_SENSE and RST_SENSE debounce
3. Remove "short-term solution to improve NVMe eject/insert glitches".
4. Tune I3C clock parameters, to be compatible with more DIMM models.
5. [154317] ECO -- 21603 -- 01.00.15(02/24/2023) -- Function-- Able to click blink or insert HDD button when system lockdown mode.
6. [152261] ECO -- 21603 -- 01.00.12 (01/17/2023) -- GUI -- Help tips doesn't has SSDP
7. [153452] [ECO] [BIOS_1.1_20230117_IPMI_01.00.14] BMC will delay 7 mins to report AC lost event after remove power cord.
8. Modify power consumption.

01.00.14 (02/10/2023)

1. Enable IPMB
2. MB primary cpld jtag port is locked
3. Short-term solution to improve NVMe eject/insert glitches.
4. Improve the problem of SMBUS reading and writing NIC card
5. Update I2C protection map
6. RAS features according to AMD_MCE(draft)_v0.3.xlsx
7. Read incorrect Power Status without AMD CPU in H13 Platfor
8. [152125] ECO --21603-- 01.00.12 -- [MEL] No related MEL log when setup SNMPv3 Auth Protocol/ Private Protocol
9. [ECO] [CPLD F5.07.28] BMC have not "Power Supply Installed" event on Health Event Log when AC onoff cycle test
10. [150432]ECO--21603--01.00.09(12/05/2022)-- It should be have "Task Message" when BIOS firmware verify and updated completed
11. [150530]ECO--21603--01.00.09(12/05/2022)--"Task Message" it's empty when BMC/BIOS generate evidence completed
12. Failed in IPMIECO TC0002, TC0019, TC2015 and error message "Cannot establish SSL connection"
13. When DIMM is inserted into position G1~F1, the incorrect DIMM name is displayed
14. [150972] ECO --21603-- 01.00.09 -- Vlan ID=1 not match with definition (check supported each field is v1.30 by redfish get BmcInfo)
15. [141588]IPMI Web - help page link confirm/ [146214]IPMI Web - help page link confirm
16. [149099] [ECO] [H13SST-G rev 1.1] BMC have record "[PWR-0028] Smart power was configured to OFF" event log when stress memory/system idle
17. Update SDR due to SSTDG_REV.4.07_06032022
18. Update SPL 01.00.23 and TEE 0100.03.43

01.00.04 (10/28/2022)

1. First release