

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

Product Name	X12DPG-U6
Release Version	1.9
Release Date	3/15/2024
Build Date	1/2/2024
Previous Version	1.6
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	<p>1.[Enhancements] Update Dx/Mx BETA microcode for IPU2023.4 Out of band for Intel-TA-00950</p> <p>2.[Enhancements] Update BIOS version to 1.9.</p> <p>3.[Enhancements] Update M87606A6_0D0003D1 microcode for Dx/Mx stepping CPU. For INTEL-SA-00950 Security Advisory to address CVE-2023-23583(8.8, High) security issue. For INTEL-SA-00960 Security Advisory to address CVE-2022-41804(6.1, Medium)security issue.</p> <p>4.[Enhancements] Update base to 5.22_WhitleyCrb_0ACMS_ICX_077 (2024.1 IPU-PV) for INTEL-SA-00960 Security Advisory to address CVE-2022-41804(6.1, Medium)security issue.</p> <p>5.[Enhancements] Updated Intel Server Platform Services for Whitley Server Platforms IPU2024.1 4.4.4.603 for INTEL-SA-00960 Security Advisory to address CVE-2022-41804(6.1, Medium)security issue.</p>

	<b>6.[Enhancements] Apply AMI LogoFAIL Vulnerability Supplement for SA50216 Security Advisory to address CVE-2023-39539(7.5, High) security issue.</b>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<b>None</b>

*Release Notes from Previous Release(s)*

**1.6(6/16/2023)**

- 1.[Enhancements] Update BIOS version to 1.5.
- 2.[Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_075 Intel 2023.2 IPU-PV, please check header for firmware revisions.
- 3.[Enhancements] Pull high GPP\_C10\_FM\_PCH\_SATA\_RAID\_KEY first before VROC key detection
- 4.[Enhancements] Update BIOS version to 1.6.
- 5.[Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_076\_BETA (IPU-PV 2023.3).
- 6.[Enhancements] Update M87606A6\_0D0003A5 microcode for Dx stepping CPU.
- 7.[Enhancements] Updated SPS 4.4.4.500.
- 8.[Enhancements] Update VROC SATA/sSATA EFI driver to VROC PreOS v8.0.0.4006 .
- 9.[Enhancements] Change the strings from "Lock mode" to "Lockdown mode".

**1.4b(4/10/2023)**

1. [Enhancements] Update BIOS version to 1.4b.
2. [Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_74 Intel BKCWW46 IPU2023.1, please check header for firmware revisions.
3. [Enhancements] Updated Intel Server Platform Services for Whitley Server Platforms IPU2023.1 4.4.4.301

**1.4a(01/18/2023)**

- 1.[Enhancements] Update BIOS version to 1.4a.
- 2.[Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_73 Intel BKCWW40 PLR3 OOB, please check header for firmware revisions. For INTEL-SA-00657 Security Advisory to address CVE-2022-21233(6.0, Medium) security issue. For INTEL-SA-00686 Security Advisory to address CVE-2021-33060(7.8, High) security issue.
- 3.[Enhancements] a) Update VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.1012 to address INTEL-TA-00692. CVE-2022-29919(7.8 High), CVE-2022-30338(6.7 Medium), CVE-2022-29508(6.3 Medium), CVE-2022-25976(5.5 Medium) b) Update VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.1012 to address Intel Virtual RAID on CPU (VROC): Data Loss Exposure Due to RAID 5 TRIM Support document #737276 c) Update VROC SATA/sSATA legacy driver to VROC PreOS v6.3.5.1003 Hot Fix to fix 10TB or higher volume drive issue.
- 4.[Enhancements] Update ucode M87606A6\_0D00037B to address below issue. For INTEL-SA-00657 Security Advisory to

address CVE-2022-21233(6.0, Medium) security issue. For INTEL-SA-00686 Security Advisory to address CVE-2021-33060(7.8, High) security issue.

5.[Enhancements] Update BPS uEFI driver to 02.00.00.3887 for IPU2022.3.

6.[Enhancements] Update DBX file to fix Secure Boot Bypass issue.

7.[Enhancements] Follow the SMBIOS template sync the chassis type from FRU0 to SMBIOS Type 03.

8.[Enhancements] Follow CPLD spec to set BIOS\_EXIT\_UBOOT and BIOS\_BOOT\_OK for VRM I2C protect

#### **1.4 (07/07/2022)**

1.[Enhancements] Update BIOS version to 1.4.

2..[Enhancements] Update 5.22\_WhitleyCrb\_0ACMS\_ICX\_72 Intel BKCWW23 PLR3, please check header for firmware revisions. For INTEL-SA-00657 Security Advisory to address CVE-2022-21233(6.0, Medium) security issue. For INTEL-SA-00686 Security Advisory to address CVE-2021-33060(7.8, High) security issue.

3.[Enhancements] Update VROC SATA/sSATA EFI driver to VROC PreOS v7.7.6.1004 to address INTEL-TA-00692. CVE-2022-29919(7.8 High), CVE-2022-30338(6.7 Medium), CVE-2022-29508(6.3 Medium), CVE-2022-25976(5.5 Medium) Update VROC SATA/sSATA legacy driver to VROC PreOS v6.3.5.1003 Hot Fix to fix 10TB or higher volume drive issue.

5.[Enhancements] Update SINIT ACM 1.1.0 and BIOS ACM 1.1.0.

6.[Enhancements] Update ucode M876CPLD06A6\_0D000375 to address below issue. For INTEL-SA-00657 Security Advisory to address CVE-2022-21233(6.0, Medium) security issue. For INTEL-SA-00686 Security Advisory to address CVE-2021-33060(7.8, High) security issue.

7.[Enhancements] Add "CSM Support" setup item into SMCISBForm page.

8.[Enhancements] If chassis type of FRU0 is not 1(other) or 2(unknown), sync it to SMBIOS type 3.

9.[Enhancements] Disable Link Re-train in BIOS to avoid secondary Bus Reset following intel MOW 22WW27 and expose Link Re-train per port in BIOS.

#### **1.2 (03/07/2022)**

1.[Enhancements] Update AMI 5.22\_WhitleyCrb\_0ACMS\_ICX\_070\_BETA RC27P52 for BKC 2021\_WW52 (PLR1)

2.[Fixes] Remove 1G option from MMCFG base to avoid system hang.

3.[Fixes] Fixed the SMBIOS event log ERROR CODE not display correctly under BIOS menu issue (EFI error type).

4.[Enhancements] Change string "VMX" to "Intel Virtualization Technology".

5.[Fixes] Fix SpeedStep (P-States) setting change when its default setting is set to Disable and load BIOS defaults in Setup.

6.[Enhancements] Update Dx/Mx microcode from Intel-Generic-Microcode-20210927\_NDA.

7.[Enhancements] Update SINIT ACM 1.0.F and BIOS ACM 1.0.E.

8.[Fixes] Fix the problem of x-AMI test failure in SmcKMS related items.

9.[Fixes] Added "Preserve\_SMBIOS", "Preserve\_OA" into FlashFlag when in the condition "NvramDefaultMode".

10.[Fixes] a) Rollback VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012 to fix system hang when VMD enable. b) Update VROC SATA/sSATA legacy driver to VROC PreOS v6.3.5.1003

11.[Fixes] Fixed issue that the OPROM control item of the riser card "RSC-H2-68G4" cannot expose in the BIOS setup menu when the system installs the AOC card "AOC-S25GC-I2S".

12.[Fixes] Fixed issue that the tests fail with the SUM ECO test cases 287 and 288 when the system connect to the Habana carrier board.

#### **1.0b (09/07/2021)**

1.[Enhancements] Disable EFI iSCSI support. (Refer Intel monthly BIOS/BMC review meeting - 7/22/2021)

- 2.[Enhancements] Patch BMC Redfish Host Interface was named as ethX when CDN was disabled case under Linux OS.
- 3.[Enhancements] Update BIOS version to 1.1b.
- 4.[Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_067 Intel BKCWW32 2021 PV MR5, please check header for firmware revisions.
- 5.[Enhancements] Update Dx/Mx microcode from Intel-Generic-Microcode-20210804\_NDA.
- 6.[Enhancements] Update BIOS/SINIT ACM 1.0.D.
- 7.[Enhancements] Updated SPS 4.4.4.58.
- 8.[Enhancements] Add flag [Preserve BIOS Boot Options Configuration] controlled by BMC/SUM
- 9.[Fixes] Add a path to check the OAM devices speed/width drop.

#### **1.0a (06/11/2021)**

- 1.[Enhancements] [X12DPG-U6] Change revision to 1.0a.
- 2.[Enhancements] Update 5.22\_WhitleyCrb\_OACMS\_ICX\_065\_BETA for Intel BKCWW20 2021 PV MR3.
- 3.[Enhancements] Update Dx/Mx microcode from Intel-Generic-Microcode-20210528\_NDA.
- 4.[Enhancements] Updated SPS 4.4.4.56.
- 5.[Enhancements] Updated BIOS ACM 1.0.A, SINIT ACM 1.0.A.
- 6.[Enhancements] Update SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012.
- 7.[Fixes] Fix SGX settings can't be preserve after updating BIOS. The function can't support IPMI web updating BIOS.
- 8.[Fixes] Fixed the AER issue of the carrier board.

#### **1.0 (04/07/2021)**

- 1. First Release.