

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H14DSG-OD</b>
<b>Release Version</b>	<b>1.3</b>
<b>Release Date</b>	<b>2/21/2025</b>
<b>Previous Version</b>	<b>1.0</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>IPMI R 01.02.04.01 or above</b>
<b>Important Notes</b>	BIOS image: BIOS_H14DSG-OD-1D72_20250221_1.3_STDsp.bin BIOS Update package: BIOS_H14DSG-OD-1D72_20250221_1.3_STDsp.zip
<b>Enhancements</b>	1. [Turin] Updated to version TurinPI_SP5_1003_Patch_1. 2. [Turin] Modified the BIOS setup variable Enable/Disable to include the "d" option. 3. [Turin] Enhanced the SMCFKItem rule for BIOS attributes. 4. [Turin] Updated the System Diagnostics module. 5. [Turin/Genoa] Set the SR/IOV setting to be enabled by default. 6. [Turin] Modified the slot mapping configuration.
<b>New features</b>	N/A
<b>Fixes</b>	1. [Turin] Fixed the issue of no IP display on early video. 2. [Turin] Fixed the issue where the system would hang when trying to enter the setup menu on the first boot. 3. [Turin]: Fixed the issue where slot 6 was mapped to the wrong device in SMBIOS type 9. 4. [Turin]: Added the missing ASPM support setting. 5. [Turin]: Fixed the default value of "Family" under DMI type 1.

*Release Notes from Previous Release(s)*

**1.0 (2/3/2025)**

First release.