IPMI Firmware / BIOS Release Notes Form

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SPI-TF
Release Version	2.0
Release Date	11/29/2017
Previous Version	1.0a
Update Category	Critical
Dependencies	None
Important Notes	N/A
Enhancements	1. Updated Purley RC 149.R09, SPS 4.0.04.294, ACM files, and CPU
	microcode.
	2. Added the "PEIIPMI Initialization" Post-Help message.
	3. Set to avoid TCG protocol "PassThroughToTpm" failure under EFI
	shell when user enables "TXT Support" with disabled "TPM state" in
	TPM 1.2 BIOS setup menu.
	4. Updated help string for tCCD relax setup option.
	5. Allowed runtime memory UCE mapout message to be displayed
	one time during BIOS POST.
	6. Hid "TXT Support" in BIOS Setup menu dynamically when CPU
	doesn't support it.
	7. Enabled display of EarlyVideo message by onboard video when
	VGA Priority is set to Offboard.

	8. Removed the "System Firmware Error (POST ERROR)" error log
	from BMC and "EFI 01030006" in BIOS event log.
	9. Added "SMBIOS Preservation" Enabled/Disabled item for flash
	recovery.
	10. Masked off PCIe correctable and non-fatal errors.
	11. Removed PCI PERR/SERR Support item and enabled reporting
	PCIe error by default.
	12. Changed BIOS revision to 2.0.
New features	1. Set to show recovery error message when no BIOS image is in USB
	pen drive.
	2. Set display of setup option for always turbo mode function as
	default.
	3. Added Run Sure setup item.
	4. Set message "BIOS cannot support downgrade to previous version
	or ROMID mismatch" to show when trying to downgrade BIOS or
	flash other model of BIOS.
Fixes	1. Fixed problem of the string of "Error DIMM information" on screen
	being corrupted when equipping failed DIMM.
	2. Updated BMC LAN configuration for saving settings of BIOS setup
	menu.
	3. Fixed inability to enter setup menu when pressing "DEL" key if
	there is no boot device.
	4. Fixed failure of SMBIOS Type 20 to fill Interleave Position and
	Interleaved Data Depth correctly.
	5. Fixed problem of the Runtime UCE memory causing DIMM mapout
	to not show on screen.
	6. Fixed the Endless reboot caused by Last-time-uncorrected-memory
	error.
	7. Fixed problem of serial console output showing SMC logo when
	EarlyVideo logo item is disabled.
I.	ı

- 8. Fixed problem of the Last UCE report (mapout) DIMM sometimes not matching real UCE DIMM location.
- 9. Fixed inability to report PCIe error event in PCH slot.
- 10. Fixed problem of IPMI SEL logging "Memory training failure." and "No memory DIMM detected, install memory DIMMs." twice per reboot.
- 11. Fixed problem of TPM 1.2 PS index not being Write-Protected so that the content of TPM 1.2 PS index still can be modified after TPM 1.2 is nvLocked.
- 12. Fixed problem of DMI being cleared when running SUM LoadDefaultBiosCfg.