IPMI Firmware / BIOS Release Notes Form

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SPL-F
Release Version	2.0
Release Date	11/29/2017
Previous Version	1.0
Update Category	Critical
Dependencies	None
Important Notes	N/A
Enhancements	1. Changed BIOS revision to 2.0.
	2. Updated 5.12_PurleyCrb_0ACFD084_BETA for Purley Skylake
	platform PLR 3.1.
	3. Updated CPU microcode SRV_P_214 for Skylake-EP H0/M0/U0
	stepping CPUs.
	4. Updated SPS XML setting for SPS 4.0.4.294.
	5. Enabled display of EarlyVideo message by onboard video when
	VGA Priority is set to Offboard.
	6. Updated BMC LAN configuration for saving settings of BIOS setup
	menu.
	7. Updated help string for tCCD relax setup option.
	8. Corrected help string of setup item "Enforce POR".
	9. Updated new MRC error log definition.

	10. Allowed runtime memory UCE mapout message to be displayed
	one time during BIOS POST.
	11. Masked off PCIe correctable and non-fatal errors.
	12. Moved Run Sure item to Memory RAS Configuration setup page.
	13. Updated SATA RAID OPROM/EFI driver to RSTe PreOS
	v5.3.0.1052.
	14. Added support for AOC-SLG3-2M2 card.
	15. Hid memory frequency 2200 and 2600.
New features	1. Removed support for Ctrl+home triggering recovery.
	2. Set display of setup option for always turbo mode function as
	default.
	3. Added the "PEIIPMI Initialization" Post-Help message.
	4. Added Run Sure setup item.
	5. Set message "BIOS cannot support downgrade to previous version
	or ROMID mismatch" to show when trying to downgrade BIOS or
	flash other model of BIOS.
Fixes	1. Fixed failure of Password Preservation Test due to password not
	being preserved.
	2. Fixed problem of "Correctable, Non-Fatal and Fatal" error reporting
	flags being disabled on "Infiniband controller: Mellanox Technologies
	MT27700 Family [ConnectX-4]" when "PCI PERR/SERR Support" is
	enabled.
	3. Fixed failure of setup item "Install Windows 7 USB support".
	4. Fixed problem of the string of "Error DIMM information" on screen
	being corrupted when equipping failed DIMM.
	5. Fixed problem of system sometimes hanging at post code B2 when
	running Cburn ONOFF.
	6. Fixed inability to enter setup menu when pressing "DEL" key if
	there is no boot device.
	7. Fixed problem of SUM GetDmiInfo command error "Invalid DMI
	information from BIOS" occurring.

	8. Fixed failure of SMBIOS Type 20 to fill Interleave Position and
	Interleaved Data Depth correctly.
	9. Corrected Hynix DIMM info as "SK Hynix".
	10. Fixed problem of IPMI SEL logging "Memory training failure." and
	"No memory DIMM detected, install memory DIMMs." twice per
	reboot.
	11. Fixed problem of TPM 1.2 PS index not being Write-Protected so
	that the content of TPM 1.2 PS index still can be modified after TPM
	1.2 is nvLocked.
	12. Corrected the "Save Changes" setup option string in "Save & Exit"
	menu.
	13. Fixed problem of system generating abnormal strings under DOS
	after triggering SERR or PERR error event in PCH slot.
	14. Fixed problem of system hanging when using AFUWIN/AFULNX to
	flash BIOS under OS.
	15. Fixed problem of DMI clearing when running SUM
	LoadDefaultBiosCfg.
L	