IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SPG-TF
Release Version	1.0a
Release Date	11/17/2017
Previous Version	1.0
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Added the "PEIIPMI Initialization" Post-Help message.
	2. Set to avoid TCG protocol "PassThroughToTpm" failure under EFI
	shell when user enables "TXT Support" with disabled "TPM state" in
	TPM 1.2 BIOS setup menu.
	3. Updated help string for tCCD relax setup option.
	4. Added setup item for Samsung tRWSR workaround.
	5. Corrected help string of setup item "Enforce POR".
	6. Updated new MRC error log definition.
	7. Allowed runtime memory UCE mapout message to be displayed
	one time during BIOS POST.
	8. Updated CPU microcode SRV_P_209 for Skylake-EP H0 stepping
	CPUs.
	9. Increased SataRaidOromDelay & SataRaidOromDelay to 6 seconds.
	10. Updated ShellBinPkg_08 for CapsLock/NumLock malfunction.

	<u></u>
	11. Reduced the boot time caused by IPv4/IPv6 polling.
	12. Added "SMBIOS Preservation" Enabled/Disabled item for flash
	recovery.
	13. Added support for AOC-SLG3-8E2P and AOC-SGL3-4E2P.
	14. Updated SATA RAID OPROM/EFI driver to RSTe PreOS
	v5.3.0.1041.
	15. Updated SPS 4.00.04.288 PLR version for security vulnerabilities.
	16. Updated BIOS ACM 1.3.4.
	17. Updated CPU microcode SRV_P_211 for Skylake-EP H0 stepping
	CPUs.
	18. Updated 5.12_PurleyCrb_0ACFD083_BETA for Purley Skylake
	Platform BKC WW39.
	19. Moved Run Sure item to Memory RAS Configuration setup page.
	20. Updated ME XML VSCC table to support 32MB SPI chip
	25L25635E/MX25L25635F/MX25L25673G.
	21. Masked off PCIe correctable and non-fatal errors.
	22. Added support for AOC-SLG3-2M2 card.
	23. Hid "Enable ADDDC Error Injection" setup item.
	24. Set PCIe correctable error to not log and legacy PCI PERR or SERR
	error to still log.
	25. Removed PCI PERR/SERR Support item and enabled reporting
	PCIe error by default.
	26. Set eSPI clock to 24MHz and added support for Quad IO mode.
New features	1. Displayed setup item "Core Disable Bitmap(Hex)" in BIOS CPU
	Configuration page.
	2. Added Run Sure setup item.
	3. Set BIOS/ME flashing to be skipped when trying to downgrade the
	SPS ME firmware from 4.0.4.288 to previous version.
Fixes	1. Corrected SMBIOS Type 9/40 information for CPU1 PCIe slot.
	2. Fixed failure of Password Preservation Test due to password not
	being preserved.
	•

- 3. Fixed problem of the string of "Error DIMM information" on screen being corrupted when equipping failed DIMM.
- 4. Updated BMC LAN configuration for saving settings of BIOS setup menu.
- 5. Fixed inability of Intel P3100 M.2 to boot to OS case.
- 6. Fixed inability to enter setup menu when pressing "DEL" key if there is no boot device.
- 7. Fixed malfunction with SMCSataFrozen item.
- 8. Fixed failure of SMBIOS Type 20 to fill Interleave Position and Interleaved Data Depth correctly.
- 9. Fixed problem of system hanging when set to NVMe VMD mode for CPU PCIe Root Port.
- 10. Fixed BMC PCIe root port being forced to Gen1.
- 11. Fixed problem of the Runtime Uncorrectable Memory error injection causing system to enter into endless reboot at POST code 0xEE.
- 12. Fixed the Endless reboot caused by Last-time-uncorrectedmemory error.
- 13. Fixed inability of Intel RC Setup strings to appear in SUM BiosCfg file when booting to OS directly.
- 14. Fixed problem of serial console output showing SMC logo when EarlyVideo logo item is disabled.
- 15. Fixed problem of the Last-runtime-memory-UCE causing system to hang at POST 0x79.
- 16. Fixed problem of CMOS write sometimes being unstable.
- 17. Fixed problem of the Last UCE report (mapout) DIMM sometimes not matching real UCE DIMM location.
- 18. Corrected Hynix DIMM info to "SK Hynix".
- 19. Fixed inability to report PCI-e error event in PCH slot.

- 20. Fixed problem of IPMI SEL logging "Memory training failure." and "No memory DIMM detected, install memory DIMMs." twice per reboot.
- 21. Fixed problem of TPM 1.2 PS index not being Write-Protected so that the content of TPM 1.2 PS index still can be modified after TPM 1.2 is nvLocked.
- 22. Fixed problem of system hanging when using AFUWIN/AFULNX to flash BIOS under OS.