## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRL-LN4 (AII)
Release Version	3.0a
Release Date	2/8/2018
Previous Version	2.0a
Update Category	Critical
Dependencies	N/A
Important Notes	ECO #20441 BIOS Image X10DRLN8.208 Please update BIOS with attached Flash Utility in package.
Enhancements	<ol> <li>Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017- 5715) security issue.</li> <li>Changed BIOS revision to 3.0a.</li> <li>Corrected POST diagnostic signOn string.</li> <li>Patched for Micron Z11C DIMM to improve the stability.</li> <li>Changed tCCD_L Relaxation default to 1 and changed string from Enabled to Auto.</li> <li>Appended VPD - VB tag in VPD-W Tag(0x91) area.</li> <li>Updated new MRC error log definition.</li> <li>Updated Intel Server Platform Services 3.1.3.38 PLR7 for Grantley Refresh Platforms.</li> <li>Added Intel SPI vulnerability patch for Grantley.</li> <li>Updated Broadwell-EP B0/M0/R0 CPU uCode MEF406F1_0B000022.</li> <li>Added "SMBIOS Preservation" Enabled/Disabled item for flash recovery.</li> <li>Enhanced SMC Recovery Flash Boot Block feature.</li> <li>Updated Intel Server Platform Services 3.1.3.50 for Grantley Refresh Platforms.</li> <li>Freed SMC Recovery Flash Boot Block feature.</li> <li>Defated SATA RAID OPROM/EFI driver to RSTe PreOS v4.7.0.1014.</li> <li>Updated Intel Server Platform Services 3.1.3.50 for Grantley Refresh Platforms.</li> <li>Removed support for using Ctrl+home to trigger recovery.</li> </ol>
	16. Updated Broadwell-EP RC 4.3.0 PLR10 release. 17. Changed Memory correctable threshold to 100 and enabled

	Cloaking for Broadwell CPU E5-26xx SKU.
New features	<ol> <li>Displayed setup item "ACS Control" to Enable/Disable PCIe Access Control Services Extended Capability.</li> <li>Added BBS reset function to SmcOobLoadBiosDefault().</li> <li>Added SumBbsSupportFlag into DAT file.</li> <li>Added support for JEDEC NVDIMM.</li> <li>Added LSI 3008/3016 HBA sensor support.</li> <li>Implemented SMC Recovery Flash Boot Block feature.</li> </ol>
Fixes	<ol> <li>Fixed issue of SUM TC306 and TC317 failing in certain configuration cases.</li> <li>Fixed problem of system hanging after Watch Dog function is enabled and then BIOS is updated.</li> <li>Fixed missing Manufacturer string in SMBIOS type 17 when Ramaxel DIMM is plugged in.</li> <li>Fixed problem of NVDIMM setup items appearing when optimized defaults load even without NVDIMM being installed.</li> <li>Fixed problem of system hanging on POST code 0xB2.</li> <li>Fixed problem of system resetting or hanging after Watch Dog function is enabled and then BIOS is updated.</li> <li>Fixed problem of system resetting or hanging after Watch Dog function is enabled and then BIOS is updated.</li> <li>Fixed inability to get correct Memory CECC DIMM location via SD5.</li> <li>Fixed problem of system hanging at 79 with some NVDIMMs.</li> <li>Fixed problem of incorrect PCI slot number showing on Legacy/UEFI mode.</li> </ol>