## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name     | X10DRL-i (All)   |
|------------------|--|
| Release Version  | 3.0a   |
| Release Date     | 2/9/2018   |
| Previous Version | 2.0b   |
| Update Category  | Critical   |
| Dependencies     | N/A  |
| Important Notes  | ECO #20440<br>BIOS Image X10DRL8.209<br>Please update BIOS with attached Flash Utility in package.   |
| Enhancements     | <ol> <li>Updated CPU microcode to address CVE-2017-5715 security issue.</li> <li>Changed BIOS revision to 3.0a.</li> <li>Updated Broadwell-EP RC 4.3.0 PLR11 release.</li> <li>Updated BIOS ACM 3.1.1 PW and SINIT ACM 3.1.1 PW.</li> <li>Added tCCD_L Relaxation item under Memory Configuration menu.</li> <li>Added SumBbsSupportFlag into DAT file.</li> <li>Changed Memory correctable threshold to 100 and enabled<br/>Cloaking for Broadwell CPU E5-26xx SKU.</li> </ol>    |
| New features     | <ol> <li>Added support for JEDEC NVDIMM.</li> <li>Implemented SMC Recovery Flash Boot Block feature.</li> </ol>  |
| Fixes            | <ol> <li>Added Ramaxel JEDEC ID to support Ramaxel memory.</li> <li>Fixed problem of NVDIMM setup items appearing when optimized defaults load even without NVDIMM being installed.</li> <li>Fixed problem of SMBIOS Type4 CPU2 current speed not showing as zero when CPU2 is not installed.</li> <li>Fixed problem of system resetting or hanging after Watch Dog function is enabled during BIOS update.</li> <li>Fixed problem of MWAIT being disabled on BSP only.</li> </ol> |