IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRX
Release Version	3.0a
Release Date	2/8/2018
Previous Version	2.0b
Update Category	Critical
Dependencies	None
Important Notes	None
	1. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v4.7.0.1014.
Enhancements	2. Updated Intel Server Platform Services 3.1.3.50 for Grantley
	Refresh Platforms.
	3. Updated CPU microcode SRV_B_204 for Haswell-EP C0,1/M0,1/R2
	& Broadwell-EP B0/M0/R0.
	4. Removed support for using Ctrl+home to trigger recovery.
	5. Changed BIOS revision to 3.0a.
	6. Changed Memory correctable threshold to 100 and enabled
	Cloaking for Broadwell CPU E5-26xx SKU.
	7. Updated Broadwell-EP RC 4.3.0 PLR10 release.
	8. Removed the "P1" string when Memory error occurs on UP server.
	9. Corrected POST diagnostic signOn string.
	10. Patched Micron Z11C DIMM to improve stability.

	11. Changed tCCD_L Relaxation default to 1 and changed string from
	Enabled to Auto.
	12. Appended VPD - VB tag in VPD-W Tag(0x91) area.
	13. Updated CPU microcode SRV_P_192 for Broadwell-EP B0/M0/R0.
	14. Updated new MRC error log definition.
	15. Updated Intel Server Platform Services 3.1.3.38 PLR7 for Grantley
	Refresh Platforms.
	16. Updated CPU microcode SRV_P_181 for Broadwell-EP B0/M0/R0.
	17. Updated CPU microcode SRV_P_182 for Haswell-EP
	C0,1/M0,1/R2.
	18. Added Intel SPI vulnerability patch for Grantley.
	19. Updated Broadwell-EP B0/M0/R0 CPU uCode
	MEF406F1_0B000022.
	20. Added "SMBIOS Preservation" Enabled/Disabled item for flash
	recovery.
	21. Enhanced SMC Recovery Flash Boot Block feature.
	1. Displayed setup item "ACS Control" to Enable/Disable PCIe Access
	Control Services Extended Capability.
	2. Added BBS reset function to SmcOobLoadBiosDefault().
	3. Added SumBbsSupportFlag into DAT file.
	4. Added support for JEDEC NVDIMM.
	5. Added support for LSI 3008/3016 HBA sensor.
New features	6. Displayed Monitor/Mwait setup item.
	7. Added ability of MECI (Multiple Event Count Increment) and METW
	(Multiple Event Time Window) to work with memory correct error
	and PCIe error reports.
	8. Added VB tag to VPD data if not already present.
	9. Implemented SMC Recovery Flash Boot Block feature.
Fixes	
	1. Fixed issue of SUM TC306 and TC317 failing in certain configuration
	cases.

	2. Fixed problem of system hanging after Watch Dog function is
	enabled and then BIOS is updated.
	3. Fixed incorrect memory error location on UP server.
	4. Fixed missing Manufacturer string in SMBIOS type 17 when
	Ramaxel DIMM is plugged in.
	5. Fixed problem of NVDIMM setup items appearing when optimized
	defaults load even without NVDIMM being installed.
	6. Fixed problem of system hanging on POST code 0xB2.
	7. Fixed problem of system resetting or hanging after Watch Dog
	function is enabled during BIOS update.
	8. Fixed inability to get correct Memory CECC DIMM location via SD5.
	9. Fixed inability to log Patrol Scrub UCE.
	10. Fixed problem of system hanging at 79 with some NVDIMMs.
	11. Applied AMI EIP EIP274689 to fix some BIOS setup items not
	working properly with default values loaded on the CPU page.
	12. Fixed issue where changes in METW or MECI values do not take
	effect in current boot to OS.
	13. Corrected MECI help string typo.
	14. Fixed system hanging at 0xA9 when the GPNV event log is full.
	15. Fixed system hanging at POST 0xB2 when installing Mellanox
	MCX311a and MCX312C-XCCT.
	16. Fixed SUM error when running "GetCurrentBiosCfgTextFile" after
	BIOS setup modified by AMIBCP.
	17. Fixed inability to change "Processor Frequency" when setting
	"Boot performance mode" to "Max Efficient" by AMIBCP.
	18. Fixed system hanging when plugging in an add-on card that
	contains non-SMC format VPD data.
	19. Fixed multiple event time count not following the specifications.
	20. Fixed problem of incorrect PCI slot number showing on
	Legacy/UEFI mode.
L	1

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print