

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|--|
| Product Name | X11SPM-F/TF/TPF |
| Release Version | 2.0b |
| Release Date | 3/13/2018 |
| Previous Version | 2.0a |
| Update Category | Critical |
| Dependencies | None |
| Important Notes | None |
| Enhancements | 1. Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue. 2. Updated BIOS version to 2.0b. 3. Updated 5.12_PurleyCrb_0ACFD085Beta for Purley Skylake platform PLR 4, BKC WW02. 4. Displayed setup item "ACS Control" to Enable/Disable PCIe Access Control Services Extended Capability, with Enabled as default. |
| New features | N/A |
| Fixes | 1. Disabled CPU2 IIO PCIe root port ACPI hot plug function. 2. Fixed issue with IPMI force boot. 3. Fixed malfunction of "SMBIOS Preservation" Disabled. |

| | |
|--|---|
| | <p>4. Fixed problem of SMC skipping first boot option in UEFI mode when retrying boot.</p> <p>5. Fixed inability to reset the system under DOS by pressing "Ctrl-Alt-Del" on USB keyboard when "Port 60/64 Emulation" is disabled.</p> <p>6. Fixed inability of some CPUs to display correct microcode revision under BIOS setup menu.</p> <p>7. Fixed inability to detect 2 NVMeS with AOC 2E2T.</p> <p>8. Fixed failure of SUM TC 219.</p> |
|--|---|