

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11SCW-F</b>
<b>Release Version</b>	<b>1.0b</b>
<b>Release Date</b>	<b>5/16/2019</b>
<b>Previous Version</b>	<b>1.0a</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Added support for Linux built-in utility efibootmgr.</li><li>2. Added support for consistent device naming for on-board devices.</li><li>3. Updated OOB module to R.1.0.1.3</li><li>4. Hid the item "Always Turbo Mode" after setting the "Turbo Mode" to disabled in Advanced/CPU Configuration page.</li><li>5. Added OEM strings to 50 bytes in type 11.</li><li>6. Added "Driver Health setup" item.</li><li>7. Added driver health warning message.</li><li>8. Renamed "AC Loss Policy Depend on" to "Restore on AC Power Loss".</li><li>9. Enhanced the solution for the error/warning message from dmidecode after AMIDE modification.</li><li>10. Enhanced Error logging for SD5.</li></ol>

	<p><b>11. Updated Coffee Lake-S R-0 stepping CPU microcode M22906ED_000000B4.</b></p> <p><b>12. Updated SPS 5.1.03.62 for INTEL-SA-00213 Security Advisory to address CVE-2019-0089, CVE-2019-0090, CVE-2019-0086, CVE-2019-0091, CVE-2019-0092, CVE-2019-0093, CVE-2019-0094, CVE-2019-0096, CVE-2019-0097, CVE-2019-0098, and CVE-2019-0099.</b></p> <p><b>13. Exposed the CPU's PL1 and PL2 items of Advanced -&gt; CPU Configuration page in the BIOS setup menu.</b></p> <p><b>14. Updated Intel RSTe RAID Option ROM/UEFI Driver to 6.1.0.1017.</b></p> <p><b>15. Updated MCU 906EA-U0 + 906EB-B0 + 906EC-P0) for INTEL-SA-00233 Security Advisory to address CVE-2018-12126, CVE-2018-12127, and CVE-2018-12130.</b></p> <p><b>16. Updated RC to version 7.0.58.41 to support 32GB of memory.</b></p> <p><b>17. Updated USB and Fastboot module.</b></p> <p><b>18. Set default setting Power Limit 2 to 150W when 8 Core CPU is used in the system.</b></p> <p><b>19. Set OptionRom and boot mode select to EFI while CSM is disabled.</b></p> <p><b>20. Changed UEFI LAN Boot option name format for SUM requirement.</b></p> <p><b>21. Added RFC3021 solution for the network stack (/32 subnet mask support).</b></p>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<p><b>1. Fixed malfunction of SR-IOV feature.</b></p> <p><b>2. Updated "Restore Optimized Defaults" string for Mehlow Server template.</b></p> <p><b>3. Modified UEFI network description to IPv4/IPv6 to follow Industry Standard.</b></p>

	<p><b>4. Removed processor version "Type" string for Mehlow Server template.</b></p> <p><b>5. Added a Disabled option for "Onboard Video Option ROM" setup item.</b></p> <p><b>6. Updated "Redirection After BIOS POST" string for Mehlow Server template.</b></p> <p><b>7. Fixed problem of BMC VGA status being enabled in SMBIOS Type 41 when JPG1 is disabled (In 2-3).</b></p> <p><b>8. Fixed lack of onboard VGA information in Type 40.</b></p> <p><b>9. Fixed problem of DIMM location showing "NO DIMM INFO" in Event log when ECC error occurs.</b></p> <p><b>10. Fixed problem of DIMM location always showing "DIMMA1" in BIOS Event log when ECC error occurs.</b></p> <p><b>11. Fixed problem of the POST screen showing "?[1;31;40m" when EFI driver is "Unhealthy".</b></p> <p><b>12. Fixed issue of system may or may not hanging up when LAN1 is disabled.</b></p>
--	--

**Release Notes from Previous Release(s)**

**1.0a (12/24/2018)**

1. Updated BIOS revision to 1.0a.
2. Updated Intel Reference Code to version 7.0.48.21.
3. Updated CPU MCUs (906EA, U0 + 906EB, B0 + 906EC, and P0).
4. Hid LAN OPRON Control items besides LAN#1 when LAN#1 OPRON is set to iSCSI.
5. Added Early Video messages when BIOS is in recovery mode.
6. Added "ACPI T-States" setup item.
7. Displayed "AERON" and "MCEON" strings during POST when "PCI AER Support" or "Memory Corrected Error" is enabled.
8. Hid "ECC Support" item.
9. Set the default of "Memory Corrected Error Enabling" to disabled.
10. Updated the Intel BIOS ACM version to 1.5.0 and SINIT ACM to 1.6.0.
11. Added "SMC SMBIOS Measurement" feature for PCR#1 measurement and enabled "Measure\_Smbios\_Tables".
12. Updated RAID option ROM and UEFI driver to 5.5.1028.
13. Added "MCEON" and "AERON" POST strings for SOL console when items are enabled.
14. Enhanced JPG1 function for running SUM with JPG1 2-3.
15. Added support for RFC4122 UUID format feature so that RFC4122 encoding from build time is produced by IPMCFG 1.29 tool or newer version.
16. Added SATA Frozen function.
17. Updated SPS firmware to SPS\_E3\_05.00.03.114.
18. Added support for Linux built-in utility efibootmgr.
19. Fixed inability of Boot Option of UEFI Application Boot Priorities to load default via Afu tool with command "/N".
20. Changed "Sata Interrupt Selection" default value to MSI.
21. Fixed problem of the status of Chassis Intru clearing in every single boot.
22. Fixed problem of serial port UID order not following COM port order after BIOS update.
23. Fixed problem of PCR#1 value changing during Legacy boot with TPM 2.0 when Measure\_Smbios\_Tables is disabled.
24. Fixed problem of the system having an exception while entering BIOS Setup with NVMe M2\*1 + SATA M2\*1.
25. Fixed problem of InBand receiving incorrect OEM FID size.
26. Fixed inability to show RSC-W-68 information when only RSC-W-68 is plugged in the SMBIOS.