## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSL-i/C/NC (All)	
Release Version	2.0b	
Release Date	12/02/2019	
<b>Previous Version</b>	2.0	
<b>Update Category</b>	Critical	
Dependencies	N/A	
Important Notes	ECO #23131 BIOS Image H11SSL9.C02_D32 Please update BIOS with attached Flash Utility in package.	
Enhancements	<ol> <li>Change BIOS revision to 2.0b.</li> <li>Add "DRAM Scrub Time" in Memory Configuration.</li> <li>Update AGESA RomePI to 1.0.0.4 based on 5.14_RomeCrb_0ACMK012.</li> <li>Use AMD CBS "PCIe ARI Support" item instead of "ARI Forwarding".</li> <li>Update item string "Input the description" and "HTTP Boot One Time" to meet Rome BIOS Setup Template v0.7_20190705.</li> <li>Show 3rd IPMI version number in BIOS setup.</li> <li>According to each project's board ID, update SSID of AMD Host Bridge.</li> <li>Expose riser card string in PCIe/PCI/PnP page when plug RSC_RR1U_E16 riser card on slot6.</li> <li>Set IOMMU default as Auto(Enabled)</li> <li>Exposed item "Preferred IO".</li> <li>(Rome CPU) Support USB recovery of Asmedia XHCI Controller and CPU USB ports for Agesa 1.0.0.1.</li> <li>(Rome CPU) Add "SMBIOS preservation" item</li> </ol>	
New features	N/A	
Fixes	<ol> <li>Do not display any AMD memory error messages during the POST phase.</li> <li>Fixed recovery function cannot work.</li> <li>Support OOB SATA HDD information and asset information of the 2 SATA controllers.</li> <li>No screen output when Boot Mode is changed to EFI.</li> <li>Fix system will hang when installing NVidia RTX 2080/5000/6000, since it will hang at accessing the card's USB MMIO address when it is set above 4G decode.</li> <li>Fixed the issue that "SMCI POST Screen Message" might be shown on the BIOS setup menu. ExitBootServices is not called on the BIOS setup menu enter. Reviewed "SMCI POST Screen Message" for creating the document.</li> <li>Fixed the issue that "SMCI POST Screen Message" might be shown on the POST screen during executing the EFI Shell application. EFI shell application might re-connect controller then a binding correct driver, it would trigger the registered SMCI DXE report handler to show "SMCI POST Screen Message" under EFI Shell.</li> <li>Fix bug that the HD Audio test of WHQL HLK with Windows Server 2019 would detect System Audio device existence to verify audio WHQL. Function disable HD Audio device to fixed the WHQL issue.</li> </ol>	

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release n	otes in italic and in smaller print
Revision 2.0 (2019/08/20)	
First release.	
Product Manager	Date