

Notes to Release Notes Authors

- All fields must be completed; please indicate as “N/A” if not applicable.
- Release Notes should document functional changes, dependencies, bug fixes and added features.
- Release Notes must not mention the methods of implementation and/or internal processes.
- Release Notes must not mention of silicon errata and/or other external causations.
- Release Notes must not mention confidential/proprietary information and/or trade secrets of Supermicro or any third party.
- Please delete this page and the signature fields before submitting the document in PDF Format to Marketing for publication.

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11QPH+
Release Version	3.3a
Release Date	7/23/2020
Build Date	7/23/2020
Previous Version	3.3
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Prevented duplicate NVMe boot options. 2. Changed BIOS Revision to 3.3a. 3. Updated Skylake-SP/Cascade Lake-SP CPU microcode from Intel-Restricted-2020-1-IPU.
New features	N/A
Fixes	1. Fixed inability of BIOS to load default when plugging in M.2. 2. Fixed CentOS boot item. 3. Fixed malfunction of secure erase when using SUM.

Release Notes from Previous Release(s)

3.3 (2/25/2020)

1. Changed BIOS Revision to 3.3.
2. Updated Intel Server Platform Services 4.1.4.381 for Purley-Refresh Platforms.
3. Updated Intel Reference Code to IPU2020.1 Rev: RC0602.D02.
4. Updated Intel BIOS ACM Firmware to v1.7.40(20190909) and SINIT ACM Firmware to v1.7.48(20191029).
5. Changed patrol scrub from uncorrectable to correctable errors.
6. Updated RSTe VMD/SATA/sATA driver to v6.2.0.1034.
7. Updated Intel Xeon microcode for Skylake-EP.
8. Added Cascade Lake Server B0 stepping CPU support.
9. Added Cascade Lake Server B1 stepping CPU support.
10. Added support for SMC HDD Security password erase and reset.
11. Added Driver Health support.
12. Added PPR test result to the System Event Log.

3.2a (1/24/2020)

1. Changed BIOS Revision to 3.2a.
2. Updated SUM with CPU 3/4 VMD configuration.
3. Changed BIOS config XML output to fix issue with Micron devices.

3.2 (11/19/2019)

1. Changed BIOS Revision to 3.2.
2. Disabled ADDDC/SDDC and set PPR as hPPR by Intel's suggestion for memory error.
3. Keep GPP_B6 high for the reboot issue.
4. Fix for changing next boot device with ipmitool. (IssueID=103477)
5. Fix for Enhanced PPR function hang issue (IssueID=102886)

Product Manager

Date