

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRFR(-N/T/NT)
Release Version	3.91
Build Date	8/6/2020
Previous Version	3.88
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	1. Fixed problem of destination address existing after updating firmware by SMCIPMITool. 2. Fixed problem of BMC web update flash firmware showing progress as 0%. 3. Fixed issues with KVM console. 4. Fixed problem add-on card SAS sensor disappearing from IPMI sensor reading.