

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H11SSW-iN/NT (All)</b>
<b>Release Version</b>	<b>1.52.12</b>
<b>Release Date</b>	<b>03/11/2021</b>
<b>Build Date</b>	<b>03/11/2021</b>
<b>Previous Version</b>	<b>1.52.09</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>ECO #25026 IPMI Image BMC_H11AST2500_6101MS_20210311_1.52.12_STD.bin Please update IPMI with attached Flash Utility in package</b>
<b>Enhancements</b>	<b>1. Improve BMC access to the system SMBus (DIMM drop when the system is reset).</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

***Release Notes from Previous Release(s)***

**Revision 1.52.09 (12/10/2020)**

1. Modified the Redfish PATCH method at `"/Systems/1/Bios"` and `"/Systems/1/Bios/SD"` to allow updating of BIOS attributes.
2. Fixed power on system onboard buzzer still beep when after trigger thermal trip event.

**Revision 1.52.00 (11/18/2019)**

1. System will not have any screen after flashing BIOS.
2. Issues on SPM REST API.
3. Improved ADMIN password is incorrect after reloading IPMI configuration.