IPMI Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	M12SWA-TF
Release Version	01.01.10
Build Date	8/7/2021
Previous Version	N/A
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	1. Fixed issue with COM1 on AST2600 A3.
	2. Fixed failure of Redfish Automation test.
	3. Fixed problem of fail message occurring when implementing
	Diagnose System under SSM_3.5.0_build.1157.
	4. Fixed failure of Automation test.
	5. Fixed failure of SUM IPMI test.
	6. Corrected display of CPU Speed on IPMI Web CPU page.
	7. Fixed failure to update BIOS and BMC under SSM_3.5.0_build.1157.
	8. Fixed missing method to check the system crash dump function.

9. Fixed failure of IPMI Hardware Monitor.
10. Fixed missing DIMM sensor reading when installing on specific
location.
11. Fixed missing PCH Fan sensor reading.
12. Fixed missing storage function for U.2 NVMe status on IPMI Web
UI.
13. Fixed failure of CPU and memory overnight stress test.
14. Fixed missing CPU TDP Watts on IPMI Web CPU page.
15. Fixed missing CPU Thermal trip event log.
16. Corrected sensor naming.
17. Fixed failure of Remote Console Preview monitor function with
User privilege account.
18. Fixed inability to test SATC Redfish automation.
19. Fixed missing Console and Crash Screen Capture function in
troubleshooting.
20. Fixed missing AOC NIC sensor and information in WebGUI.
21. Fixed missing Storage sensor and information page in WebGUI.
22. Fixed missing GPU sensor and information in WebGUI.
23. Fixed failure of BIOS update via IPMI Web.
24. Fixed problem of VDDCR Voltage sensor error occurring.
25. Fixed failure of COM1/2 loopback test.