

## BMC Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPT-PT6</b>
<b>Release Version</b>	<b>01.02.01</b>
<b>Release Date</b>	<b>10/02/2021</b>
<b>Previous Version</b>	<b>01.01.09</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Cut length of network AOC firmware version.</li><li>2. Added support for EUI-48 Locally Administered MAC Address for Redfish host interface so that Host interface can get IP in client OS after rebooting OS or removing/inserting rndis driver.</li><li>6. Made Rollback ID alert a tooltip.</li><li>7. Set Rollback ID checkbox for motherboard CPLD to disabled when license is unactivated.</li><li>7. Added querying stored rollback ID.</li></ol>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Corrected information of WebGUI.</li><li>2. Fixed problem of "Update Failed..." appearing after ROM update for RAID controller.</li></ol>

	<p><b>3. Fixed abnormality of iKVM after changing language from English to ????.</b></p> <p><b>4. Fixed problems of BRCM3808 HDD detection error occurring and HDD blink/unblink requiring DCMS license.</b></p> <p><b>5. Corrected number of SATA drives on Broadcom rectangle.</b></p>
--	--

*Release Notes from Previous Release(s)*

**01.01.09 (08/13/2021)**

- 1. Set prompt to reboot system to show after updating NICs and Broadcom firmware.*
- 2. Fixed problem of BMC WebUI logging out immediately after logging in BMC WebUI.*
- 3. Upgraded Dropbear to version 2019.78.*
- 4. Corrected information on WebGUI.*
- 5. Fine tuned firmware update process.*

**01.01.00 (06/03/2021)**

Initial release.