## **BMC Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B12DPE-6
Release Version	01.02.04
Build Date	10/27/2021
Previous Version	01.01.12
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol> <li>Removed MouseMode, iKVM, and Snooping license check.</li> <li>Set Directory Service to support group only.</li> </ol>
New features	<ol> <li>Added support for EUI-48 Locally Administered MAC Address for Redfish host interface.</li> <li>Added restore boot configuration during BIOS update.</li> <li>Set restore boot option as default if BIOS update is not set to PreserveBOOTCONF.</li> </ol>
Fixes	<ol> <li>Properly disable functions for User privilege.</li> <li>Corrected inability to unlock an Admin account using another Admin account.</li> <li>Corrected drive blink LED function on logical view page</li> <li>Prevent Delete option from being missing for RAID volumes.</li> <li>Correct situations when uploading firmware would stop.</li> <li>Correct graphical elements in Storage Monitoring.</li> <li>Corrected incorrect BMC web description in certain situations.</li> <li>Properly show power consumption after after stress tests.</li> <li>Correctly preserve SMBios when updating BIOS via</li> </ol>

/redfish/v1/UpdateService/Actions/UpdateService.SimpleUpdate.
10. Properly show link status on network AOCs.
11. Correct sluggishness of CPU page on webUI.
12. Correct typo for RollbackID.
13. Correct network AOC firmware version length.
14. Fix User-level permissions.
•
15. Corrected missing NIC sensor readings.
16. Fixed failure to run IPMIECO Automation test (TC401/402).
17. Corrected sensor name reported by HDD event.
18. Disallow changing user privilege user ID/password is empty.
19. Enabled PFR Recover Action with DCMS License on Firmware
Inventory.
20. Prevent HTML5 console reconnect while iKVM is being reset.
21. Sync password requirements.
22. Unswap B12SPE NIC1 and NIC2 MAC addresses.
23. Correct clear IPv6 address list behavior.