

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12DSi-N6/NT6
Release Version	2.3
Release Date	4/9/2021
Previous Version	2.0
Update Category	Recommended
Dependencies	IPMI FW 1.00.19
Important Notes	BIOS Image: BIOS_H12DSI-1C22_20211021_2.3_STDsp.bin BIOS Update Package: BIOS_H12DSI-1C22_20211021_2.3_STDsp.zip
Enhancements	<ol style="list-style-type: none">1. Changed BIOS revision to 2.3.2. Updated AGESA RomePI to 1.0.0.C.3. Exposed Setup item "Enhanced Preferred IO Mode".4. Updated AGESA MilanPI to 1.0.0.6.5. Patched case of BMC Redfish Host Interface being named ethX when CDN is disabled under Linux OS.6. Disabled EFI iSCSI support.7. Exposed Setup items "BankGroupSwapAlt", "SEV-SNP Support", "Enhanced Preferred IO Mode", and "Root Complex 0x00~0xE0 LCLK Frequency".8. Changed default of "Wait For "F1" If Error" to Disable.9. Updated B0 Milan microcode 0x0A00104C, B1 Milan microcode 0x0A001143, and B2 Milan-X microcode 0x0A001223 to patch Erratum #1381 problem of processor hanging when coherency probe hits instruction cache line while evicted.10. Added Redfish/SUM Secure Boot feature and updated OOB for secure boot and reserve Key.11. Added support for SUM upload/delete HTTPS TLS certificate (Default Enabled by TOKEN "Sum_UploadTlsKey_SUPPORT").12. Set Relaxed Ordering default to Enabled.13. Set all OPROM control items to Legacy when boot mode is set to Dual.14. Removed legacy iSCSI support of H12 BIOS.15. Added force next boot to UEFI Shell support.
New features	N/A

Fixes	<ol style="list-style-type: none">1. Fixed missing sensor information on IPMI WebGUI.2. Fixed problem of AFU being used to clear event log and then AC cycling the system after BIOS recovery.
-------	---

Release Notes from Previous Release(s)

2.0 (4/09/2021)

Initial Release