BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPW-(T)F
Release Version	1.1c SPS 4.4.4.58
Release Date	11/8/2021
Build Date	11/8/2021
Previous Version	1.1a
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Updated BIOS version to 1.1c.
	2. Updated 5.22_WhitleyCrb_0ACMS_ICX_069 Beta Intel BKCWW39
	2021 PV MR7, please check header for firmware revisions.
	3. Updated Dx/Mx microcode from Intel-Generic-Microcode-
	20210927_NDA.
	4. Updated BIOS ACM to 20210720 (1.0.D) and SINIT ACM 20210827
	(1.0.F).
	5. Updated SPS 4.4.4.58.
	6. Exposed the "Data Link Feature Exchange" BIOS setting in PCIe
	SLOT pages.
New features	N/A

Fixes	1. Removed the 1G option from MMCFG base to avoid system hang.
	2. Updated BMC boot status to indicate that the ROM is being flashed
	at a different memory location.
	3. Updated SmcOutBand in SmcPKG/Module/SmcOOB to allow the
	DMI data to be stored when executing "SUM -c LoadDefaultBiosCfg".

Release Notes from Previous Release(s)

1.1a (3/5/2021)

- 1. Updated BIOS version to 1.1a.
- 2. Updated 5.22_WhitleyCrb_OACMS_ICX_066 Intel BKCWW24 2021 PV MR4, please check header for firmware revisions.
- 3. Updated Dx/Mx microcode from Intel-Generic-Microcode-20210701_NDA.
- 4. Updated SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012.
- 5. Added support to riser card RSC-W2R-666G4.
- 6. Disabled EFI iSCSI support.
- 7. Path BMC Redfish Host Interface was renamed as ethX for the case where CDN was disabled under Linux OS.
- 8. Corrected SMBIOS Type41 information.