

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPW-(T)F
Release Version	1.2 SPS 4.4.4.62
Release Date	2/14/2022
Build Date	2/14/2022
Previous Version	1.1c
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated BIOS version to 1.2. 2. Updated AMI 5.22_WhitleyCrb_0ACMS_ICX_070_BETA RC27P52 for BKC 2021_WW52 (PLR1), and RC27P56 for PLR1 HF. 3. Changed string "VMX" to "Intel Virtualization Technology".
New features	N/A
Fixes	1. Removed 1G option from MMCFG base to avoid system hang. 2. Fixed the SMBIOS event log ERROR CODE that is not displaying correctly under BIOS menu issue (EFI error type). 3. Fixed SpeedStep (P-States) setting change when its default setting is set to Disable, and load BIOS defaults in Setup. 4. Rolled back VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012 to fix system hang when VMD is enabled.

Release Notes from Previous Release(s)

1.1c (11/8/2021)

1. Updated BIOS version to 1.1c.
2. Updated 5.22_WhitleyCrb_OACMS_ICX_069 Beta Intel BKCWW39 2021 PV MR7, please check header for firmware revisions.
3. Updated Dx/Mx microcode from Intel-Generic-Microcode-20210927_NDA.
4. Updated BIOS ACM to 20210720 (1.0.D) and SINIT ACM 20210827 (1.0.F).
5. Updated SPS 4.4.4.58.
6. Exposed the "Data Link Feature Exchange" BIOS setting in PCIe SLOT pages.
7. Removed the 1G option from MMCFG base to avoid system hang.
8. Updated BMC boot status to indicate that the ROM is being flashed at a different memory location.
9. Updated SmcOutBand in SmcPKG/Module/SmcOOB to allow the DMI data to be stored when executing "SUM -c LoadDefaultBiosCfg".

1.1a (3/5/2021)

1. Updated BIOS version to 1.1a.
2. Updated 5.22_WhitleyCrb_OACMS_ICX_066 Intel BKCWW24 2021 PV MR4, please check header for firmware revisions.
3. Updated Dx/Mx microcode from Intel-Generic-Microcode-20210701_NDA.
4. Updated SATA/sATA EFI driver to VROC PreOS v7.6.0.1012.
5. Added support to riser card RSC-W2R-666G4.
6. Disabled EFI iSCSI support.
7. Path BMC Redfish Host Interface was renamed as ethX for the case where CDN was disabled under Linux OS.
8. Corrected SMBIOS Type41 information.