

IPMI Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPL-(LN4)F
Release Version	01.01.17
Build Date	03/04/2022
Previous Version	01.00.21
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Supports new group sensor design.
New features	N/A
Fixes	<p>Fixed the following issues:</p> <ol style="list-style-type: none">1. Added option in BMC UI to create disabled user or edit user to disable.2. Storage feature broken in 01.01.10.3. STD -- 17212 -- 01.01.04 – [Security] Specific strings could brute force the BMC directory.4. IPMItool can set LAN mode out of range

	<p>5. [BMC-Intel VROC 7.5 OOB] Grey out "Create Raid" icon if no more physical drive available to create new Raid volume.</p> <p>6. Can't sync NTP server when BMC has IPv6 DNS</p> <p>7. Password is wrong if it contains "\ a backslash.</p> <p>8. Cross scripting vulnerability: XSS attack at Notification Alert Redfish protocol.</p> <p>9. LDAP Search Base with lots of garbage characters are appearing out of WEB UI field.</p> <p>10. Support Preserve BIOS Boot Options Configuration when updating BIOS FW.</p> <p>11. During fwUP, bmc reset, fan speed should remain the same.</p> <p>12. An inaccurate popup message when setting a user password the same as user name.</p> <p>13. Adjusted Max number of SEL up to 4096.</p> <p>14. IPMI ECO Update BIOS failure.</p> <p>15. All Broadcom AOC controllers such as 3008, 3616, 38xx and 39xx are not discoverable.</p> <p>16. Unspecified Event Log Assertion When AC ON.</p> <p>17. iKVM(JAVA plug-in/HTML5) should be support IMA file type. [137280] ECO--15340-- 01.01.13(01/27/2022) -- iKVM(JAVA plug-in) should be support "IMA" image.</p> <p>18. GPUs missing under GPU tab in IPMI Web GUI [137010] GPU and CPU liquid cooling pump SEL error in Liquid cooled system, and no GPUs detected</p> <p>19. Add SNMP type user does not have an asterisk * to inform Auth Key and Private Key are required items.</p> <p>20. Language Change title string not translated.</p> <p>21. Improve PSU initialization code, add delay and retries.</p> <p>22. Create new user on web UI should not get error, even though the user ID is occupied on NoAccess user.</p>
--	--

	<p>23. It should not present "Delete" icon while login "Operator" or "User" privileges account. [138112] ECO--15340-- 01.01.16 (02/15/2022) -- Modify password while login "Operator" or "User" privileges account will return Oops error!</p> <p>24. No GPU found on WEB BMC.</p> <p>25. [Redfish API Automation test failed]</p> <p>26. Mount failed pop up error message and Even log are incorrect.</p> <p>27. Mount *.img displaying wrong file type on Java iKVM Virtual Media.</p> <p>28. Updating invalid FW will show MEL message when updating BIOS and CPLD.</p>
--	---