

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Product Name | X12DPG-QT6 |
| Release Version | 1.4 |
| Release Date | 07/12/2022 |
| Build Date | 07/12/2022 |
| Previous Version | 1.2 |
| Update Category | Critical |
| Dependencies | None |
| Important Notes | None |
| Enhancements | <p>1.[Enhancements] Update 5.22_WhitleyCrb_0ACMS_ICX_72 Intel BKCWW23 PLR3, please check header for firmware revisions.</p> <p>2.[Enhancements] Update VROC SATA/sSATA EFI driver to VROC PreOS v7.7.6.1004 to adress INTEL-TA-00692. CVE-2022-29919(7.8 High), CVE-2022-30338(6.7 Medium), CVE-2022-29508(6.3 Medium), CVE-2022-25976(5.5 Medium)</p> <p>3.[Enhancements] Update 5.22_WhitleyCrb_0ACMS_ICX_71 Intel BKCWW18 2022 PLR2, please check header for firmware revisions.</p> <p>4.[Enhancements] Update BPS uEFI driver to 02.00.00.3886 for IPU2022.2.</p> <p>5.[Enhancements] Add "CSM Support" setup item into SMCISBForm page.</p> <p>6.[Enhancements] Filter Dynamic TCG Security Pages to patch SUM ChangeBiosCfg failed problem</p> |

| | |
|---------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | <p>7.[Enhancements] Update VROC SATA/sSATA legacy driver to VROC PreOS v6.3.5.1003 Hot Fix to fix 10TB or higher volume drive issue.</p> <p>8.[Enhancements] If chassis type of FRU0 is not 1(other) or 2(unknown), sync it to SMBIOS type 3.</p> |
| New features | N/A |
| Fixes | |

Release Notes from Previous Release(s)

1.4 (02/14/2022)

- 1.[Enhancements] Update AMI 5.22_WhitleyCrb_OACMS_ICX_070_BETA RC27P52 for BKC 2021_WW52 (PLR1)
- 2.[Enhancements]Change string "VMX" to "Intel Virtualization Technology".
- 3.[Fixes] Remove 1G option from MMCFG base to avoid system hang.
- 4.[Fixes] Fixed the SMBIOS event log ERROR CODE not display correctly under BIOS menu issue (EFI error type).
- 5.[Fixes] Correct "PCIe ASPM Support (Global)"" default value to disable.
- 6.[Fixes]Rollback VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012 to fix system hang when VMD enable.

1.1 (04/09/2021)

- 1.[Enhancements] Updated BIOS ACM 1.0.9, SINIT ACM 1.0.9
- 2.[Enhancements] Updated SPS 4.4.4.53.
- 3.[Enhancements] Update SATA/sSATA EFI driver to VROC PreOS v7.5.0.1152.
- 4.[Enhancements] The system cannot boot into PXE with DVD installed.
- 5.[Enhancements] Keep setup string of BiosVersion, BiosDate, Manufacturer and Product as default value including modification of AmiBcp.
- 6.[Enhancements] Add code to stop AFU support.
- 7.[Enhancements] Default enable BootGuard function.
- 8.[Enhancements] Extend memory DIMM serial number information.(Samsung, Micron, Hynix)
- 9.[Enhancements] Enhance Smc Dcpmm feature.
- 10.[Enhancements] Automatically disable and grayed out ADDDC, UMA-Base Clustering, mirror mode and enable NUMA when SGX enabled.
- 11.[Enhancements] Remove intel lan memory 4G limit if boot mode is not legacy.
- 12.[Enhancements] Set all oprom control items to Legacy when boot mode set to Dual.
- 13.[Enhancements] Update for 20P95_LB62_PreDrop_V1 for BKC WW15 (20P95)
- 14.[Enhancements] Update Intel-Generic-Microcode-20210226a_NDA and Intel AE (updated)
- 15.[Fixes] Fix "Configuration Address Source" always show "DHCP" in IPMI IPv6 page.
- 16.[Fixes] Fix Memory correct error location is wrong in BIOS event log for CPU2.
- 17.[Fixes] Modify Ipv6 behavior, remove error message when Ipv6 router IP is :::::
- 18.[Fixes] Correct CPU1 memory type 20 handler point to CPU2 Memory Array Mapped Address structure
- 19.[Fixes]Fix IPv6 Status show incorrect after updating BIOS.
- 20.[Fixes] Fixed IPv4 address source status show incorrect after updating BIOS issue.
- 21.[Fixes] Fixed the HDD security menu will not show when connect more than 6 HDD on system.

- 22.*[Fixes] Fix IPV6 disable in the IPMI GUI but BIOS initialize will appear IPV6 address..*
- 23.*[Fixes] Filter Dynamic HDD Security Pages to patch SUM ChangeBiosCfg failed problem.*
- 24.*[Fixes] Fixed UEFI OS boot option name shows incorrectly in BIOS setup.*
- 25.*[Fixes] Fix T-states always show 15 levels even T-state is disabled.*

1.0 (12/02/2020)

- 1. *First Release.*