## **BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPT-PT		
<b>Release Version</b>	1.4		
Release Date	7/12/2022		
<b>Build Date</b>	7/12/2022		
Previous Version	1.0		
Update Category	Recommended		
Dependencies	None		
Important Notes	None		
Enhancements	<ol> <li>Updated BIOS version to 1.4.</li> <li>Updated 5.22_WhitleyCrb_0ACMS_ICX_72 Intel BKCWW23         PLR3 (please check header for firmware revisions). For INTEL-SA-00657 Security Advisory to address CVE-2022-21233(6.0, Medium) security issue. For INTEL-SA-00686 Security Advisory to address CVE-2021-33060(7.8, High) security issue.     </li> <li>Updated VROC SATA/sSATA EFI driver to VROC PreOS v7.7.6.1004 to adress INTEL-TA-00692. CVE-2022-29919(7.8</li> </ol>		
	High), CVE-2022-30338(6.7 Medium), CVE-2022-29508(6.3 Medium), CVE-2022-25976(5.5 Medium) Updated VROC SATA/sSATA legacy driver to VROC PreOS v6.3.5.1003 Hot Fix to fix 10TB or higher volume drive issue.  4. Added "CSM Support" setup item into SMCISBForm page.		

	5.	Updated ucode M87606A6_0D000375 to address the
		following issue: For INTEL-SA-00657 Security Advisory to
		address CVE-2022-21233(6.0, Medium) security issue. For
		INTEL-SA-00686 Security Advisory to address CVE-2021-
		33060(7.8, High) security issue.
	6.	If chassis type of FRU0 is not 1(other) or 2(unknown), it will
		now be synced to SMBIOS type 3.
	7.	Disabled Link Re-train in BIOS to avoid secondary Bus Reset
		following Intel MOW 22WW27 and expose Link Re-train per
		port in BIOS.
New features	None	
Fixes	None	