BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DET-B
Release Version	1.0a SPS: 6.0.3.271
Build Date	11/03/2022
Previous Version	1.0
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Changed BIOS Revision to 1.0a.
	2. Updated AMI label to 5.29_EagleStreamCrb_0ACOR_066.
	3. Enhanced BiosCfg to show Sum GetBiosCfg when booted to
	setup menu.
	4. Enhanced tool to support user disable for "CPU C1 auto
	demotion".
	5. For chassis types "unknown" or "other", synchronization is
	performed from FRU0 to SMBIOS Type 03.
	6. Added and enabled TOKEN "SMC_HECI_HIDE_DELAY" to
	control the HECI-x hide delay to patch some unexpected
	behavior (system hang, system reboot etc.).
	7. Updated Supermicro KMIP form.
	8. Updated AST2600 VBIOS and VGA uEFI driver to 1.13.01.
	9. Enhanced tool to force PE3 port A to gen4 when UPI3 is
	enabled.
	10. Enhanced tool to automatically create UEFI OS name for
	removable device (USB key).
	11. Removed "Supermicro Security erase" page from HII format.

	12. Added SecureBoot Database to meet Redfish specification and
	single key Delete function.
	13. Discarded duplicate MAC address from Redfish interface.
	14. Updated SPS 6.0.3.271 2S PC Hotfix Release for Eaglestream
	Platforms.
	15. Added support for BIOS POST Progress in Redfish.
New features	1. Added new feature to set BIOS_EXIT_UBOOT/BIOS_BOOT_OK
	at end of POST
Fixes	1. Fixed the problem that the password could not be saved after
	the NVRAM module updated label 26.
	2. Fixed issue with Memory serial number of SMBIOS type 17 not
	matching with memory DIMM bar code.
	3. Fixed issue with SUM update DMI data setting every DMI
	value.
	4. Corrected VMD mapping in backplane CPLD register.

Release Notes from Previous Release(s)

1.0 (06/28/2022)

1. First release based on BKCWW25 2022.