

BMC FW Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPU-6
Release Version	01.01.35
Build Date	11/23/2022
Previous Version	01.01.24
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none"> 1. Improved the stability of BIOS related ROT operations. 2. Avoided ME hang during BIOS-cloning-GOLDEN operations. 3. "STD -- 01.01.24 – Incorrect MEL once set SNMPv2 to empty" "STD – 01.01.06 – Incorrect MEL when set SNMPv2 info to empty" "STD – 16416 – 01.01.23 – Incorrect MEL once set SNMPv2 to empty" 4. Failed to mount virtual media drive via WebGUI. 5. Tuned VBAT voltage sensor threshold for: VBAT_LOW=2.7V VBAT_CRITICAL=2.5V 6. Redfish HA-RAID missing IndicateActionInfo data. 7. OEM – Beiliande – 19018 –11.01.26(09/30/2022) –"VLAN ID" default value should be preset to "1", not empty. 8. i2cmap protection review 9. STD – 16728 – 01.01.30 (09/02/22) – [iKVM] Error does not exist for mounting an ISO file that has been uploaded before the ISO image has been moved. 10. STD – 16914 – 01.01.30 – Incorrect error message for CD-ROM path to image textfield. 11. [IPMI] IPMI ejected all 22x NVMe at once. WebGUI shows "failed to eject" multiple slots and displays ok after page "Refresh".