BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

X12STH-F LN4F SYS
1.13.08
12/16/2022
1.13.04
Recommended
None
None
 Modified Dedicated Link options: Add 1G Full and remove 10M Half/Full except X12STD-F and X12STE-F. * X12STD-F Dedicated Link is fixed in Auto Negotiation. * X12STE-F Dedicated Link is fixed in 1G Full. * X12DPFR-AN6 Dedicated Link is fixed in 100M Full. Optimized execution time on VRM utility.
None
 Network IPv4 DNS Server2 IP stays at 0.0.0.0 after saving a valid IP. Function Can't get system log on syslog. There is no Sensor Reading and GPU info in the BMC webUI. VRM utilities can be used on X11QPH+ when the battery is installed. Maintenance event log display error at /cgi/op.cgi (config_smtp).

- 6. Auth key and Private Key should be "Required" field and with an asterisk (*) mark. A username should not allow the use of special characters. A pop-up error message appears when typing invalid special characters for an SNMPv3 username. Trap Community should be "Required" field and with an asterisk (*) mark. Fields name mismatch SPEC of Authentication/Encryption key and Protocol.
- 7. SNMPv3 auth protocol name is not the same between 'Modify Alert' page and 'Alert' page.
- 8. Special query caused 500 Internal Server Error at X12 redfish (\$expand).
- Power Average Usage reading value is higher than Max Peak value under Power Consumption
- 10. Active Directory Remote Group character cap too short.
- 11. MEL should log BMC firmware was updated successfully.