

## BMC Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13SEI-F/TF</b>
<b>Release Version</b>	<b>1.00.44</b>
<b>Build Date</b>	<b>2/3/23</b>
<b>Previous Version</b>	<b>N/A</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. If the BMC hostname contains the @ symbol, it will be a wrong value at X13 [148012] STD – 17212 – 01.01.13 -- [Security] Unrestricted input on parameter bmcipv6_dns_server in the Network Configuration at X13 2022_08_03 [148010] STD – 17212 – 01.01.13 -- [Security] Unrestricted input on parameter bmcipv6_addr in the Network Configuration at X13 2022_08_03.</li><li>2. Removed the "PMEM Temp" sensor on X13SEW and X13SEI by the PM's request.</li><li>3. ITOS Memory UECC Error Check by Linux SW fail due to the memory map out failure.</li><li>4. SUMECO TC5003.</li><li>5. webGUI MB cpld fwUP.</li><li>6. Disabled TLSv1.0 and TLSv1.1.</li></ol>