BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name | X13SEFR-A |
|-------------------------|---|
| Release Version | 1.1 SPS: 6.0.4.025 |
| Release Date | 1/19/2023 |
| Build Date | 1/19/2023 |
| Previous Version | 1.0a |
| Update Category | Recommended |
| Dependencies | None |
| Important Notes | None |
| Enhancements | Updated AMI label to 5.29_EagleStreamCrb_OACOR_071_BETA. Updated SPS 6.0.4.25 2S PV Hotfix Release for EagleStream Platforms. Updated 806F8 Intel(R) Processor SPR E-Stepping mircocode 2B000161 and HBM B-Stepping microcode 2C000120. Followed the BIOS Setup Template v1.1 to hide the UPI3 feature in UP projects. |
| New features | None |
| Fixes | None |

1.0a (12/2/2022

- 1. Updated AMI label to 5.29_EagleStreamCrb_0ACOR_068_BETA.
- 2. Updated the VROC SATA/sSATA EFI driver to VROC PreOS v8.0.0.4006 PV.
- 3. Updated SPS 6.0.3.273 2S PC Hotfix Release for Eagle Stream Platform to address the issue where the firmware enters Recovery Mode while certain NVMe drives are attached.
- 4. Updated AST2600 VBIOS and VGA UEFI driver to 1.13.01.
- 5. Followed the Intel PTU doc to expose "CPU C1 Auto Demotion" for user disable.
- 6. Updated the DBX file to fix a Secure Boot Bypass issue.
- 7. Created the UEFI OS name to automatically support a removable device (USB key).
- 8. Followed BMC_Network_AOC_Monitoring_Spec_v2.2 to discard sending AIOM LAN MAC to BMC.
- 9. Updated BIOS revision to 1.0a.
- 10. Fixed the AFU return error that appeared when using the /N or /clnevnlog commands.
- 11. Enabled the password to be saved when the PCIe resource causes the system to reboot.
- 12. Matched the SMBIOS type 17 memory serial number to the memory DIMM bar code.

1.0 (7/29/2022)

1. First release.