

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DSC-6
Release Version	1.4b SPS: 4.4.4.301
Build Date	1/24/2023
Previous Version	1.4
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated 5.22_WhitleyCrb_0ACMS_ICX_74 Intel BKCWW46 IPU2023.1, please check header for firmware revisions.2. Updated Intel Server Platform Services for Whitley Server Platforms IPU2023.1 4.4.4.3013. Updated VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.10124. Updated M.2 slot BDF for OPROM control and SMBIOS BDF by following AOM silkscreen.
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed an issue where memory errors were not being reported in the SMBIOS event log.

Release Notes from Previous Release(s)

1.4 (7/12/2022)

1. Updated SmcOOB to the version "_SMCOOBV1.01.25_" to fix the unexpected system-resetting when loading NVRAM defaults.
2. Updated 5.22_WhitleyCrb_OACMS_ICX_72.1 Intel BKCWW23 PLR3.
3. Updated VROC SATA/sSATA EFI driver to VROC PreOS v7.7.6.1004 to adress INTEL-TA-00692.
4. Added support for IPMI PXE boot to all LAN ports feature for both Legacy and UEFI PXE.
5. Added Link Retrain per port item in BIOS.

1.2 (3/5/2022)

1. Updated AMI 5.22_WhitleyCrb_OACMS_ICX_070 RC27P56 to BKC 2021_WW52 (PLR1 HF).
2. Added flag [Preserve BIOS Boot Options Configuration] controlled by BMC/SUM.
3. Changed string "VMX" to "Intel Virtualization Technology".
4. Change BIOS revision to 1.2.
5. Removed 1G option from MMCFG base to avoid system hang.
6. Fixed the SMBIOS event log ERROR CODE which is not displaying correctly under BIOS menu issue (EFI error type).
7. Fixed SpeedStep (P-States) setting, changed when its default setting is set to Disable, and load BIOS defaults in Setup.
8. Fixed COM port resource that can't be changed and item's behavior failure.

1.1a (7/21/2021)

1. Updated 5.22_WhitleyCrb_OACMS_ICX_066_BETA Intel BKCWW24 2021 PV MR4.
2. Updated Dx/Mx microcode from Intel-Generic-Microcode-20210701_NDA.
3. Updated SmcOOB module to 1.01.24 to support SUM clean SMBIOS Event log through BiosCfg header flag.
4. Corrected firmware version and vendor on Trusted Computing page.