

BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPM-TF/LN4F/LN6TF
Release Version	1.01.41
Build Date	3/17/2023
Previous Version	1.01.34
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Modified Dedicated Link options: Add 1G Full and remove 10M Half/Full except X12STD-F and X12STE-F. X12STD-F Dedicated Link is fixed in Auto Negotiation. X12STE-F Dedicated Link is fixed in 1G Full.2. Syslog packet not follow RFC3164 Copy Project Issue Link.
New features	
Fixes	<ol style="list-style-type: none">1. SNMPv2 Community String in WEB Help does not match with the spec.2. LDAP failed to login when LDAP server has an entry limit.3. WEB -- Should have "*" if the blank is required to fill in. (Directory Service).4. WEB -- Sensor name does not match with the spec.5. hex-to-dec conversion of SGX epoch display.6. Network number mismatch during AC on/off stress.7. SNMPv2 Community String follows spec in help page.8. Web [MEL-0080] description does not match with the spec. Wrong MEL event when setting up the SMTP Alert.9. Disabled TLSv1.0 and TLSv1.1.10. Sensor naming does not match with the sensor specification.

