

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SET-G
Release Version	1.2
Release Date	03/23/2023
Build Date	03/23/2023
Previous Version	1.1a
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Intel BKC 2023_WW09, Intel RC Version 9409.P31 MR2, and HBM PV.
New features	N/A
Fixes	1. AOC-A25G-i2SM and AOC-A25G-M2SM SMBIOS report incorrectly when located at Rear I/O AIOM1.

1.1a (3/3/2023)

1. Updated Intel BKC 2023_WW07, Intel RC Version 9409.P19.
2. Exposed and adjusted the MMRS item to fine tune Gen5 performance.
3. Fixed the FWTS and WHQL fail issue.
4. Used Supermicro's defined GUID for compatibility between SuperBIOS and AMI.
5. Fixed Type 17, which did not follow SPD Spec MemoryChannelBusWidth.
6. Exposed the CPU feature, "Optimized Power Mode."
7. Updated the SATA SGPIO Mode option strings for all SATA configuration menus.
8. Followed BIOS Setup Template v1.1 to hide the "UPI3" feature in UP projects.
9. Hid the "Homeless Prefetch" feature.
10. Updated SPS 6.0.4.25 2S PV Hotfix Release for EagleStream platforms.
11. Corrected gPayloadOffset definition to fix the inability to successfully program NVRAM with AFU utility.
12. BIOS POST Progress Support requirement in Redfish.
13. Followed BMC_Network_AOC_Monitoring_Spec_v2.2 to avoid sending the AIOM/AOC IO Module LAN MAC to BMC.
14. Removed the "Supermicro Security erase" page from HII format.
15. Followed the setup template to expose the Consistent Device Name Support" feature when SMC_CONSISTENT_DEVICE_NAME_SUPPORT is enabled.
16. Updated the AST2600 VBIOS and VGA UEFI driver to 1.13.01.
17. Created UEFI OS name on the boot option for removable devices.
18. Converted "Supermicro Security Erase Configuration" page to JSON format.
19. Added SecureBoot Database to meet the Redfish specifications.
20. Created SmcKMSOBB to prepare the VFR/UNI and to create the ConfigAccess Protocol which will be used when transferring files to JSON format. Commented out the extra "Supermicro KMIP Form" when using the SUM utility to generate BIOS config file.
21. Transferred Supermicro HTTP BOOT MAIN" page (HTTPS TLS certificate upload/delete via SUM/BMC) from HII to JSON format.
22. Fixed the AFU return error that appeared when using /N or /clevnlog commands.
23. Made Enable the default TOKEN "SMC_HECI_HIDE_DELAY"(HECI-x hide delay) for all projects to fix BSOD issue.
24. Exposed the "Equalization Bypass To Highest Rate" feature.
25. Automatically hid the ADDDC Sparing feature with x8 width DIMMs.
26. Exposed "CXL Type 3 Legacy", "CXL Security Level" and "CXL Header Bypass" features for CXL.
27. Revised the code for NVMe PCC init.
28. Updated PCIe riser card support to include CBL-ASMC-1321DM5YP.
29. Enhanced the BIOS setup string and SMBIOS for different system configurations.
30. Fixed the issue where M.2 devices did not appear when setting up the VMD mode from PCH.
31. Enhanced front IO naming on BIOS setup.
32. Enhanced SMBIOS data when installing AIOM card.
33. Swapped the Slot ID for front IO AIOM slot.
34. Enhanced reporting SMBIOS type40 data.
35. Revised the Legacy intergroup that can't be listed in order.
36. Fixed the WHQL HSTI Rollback firmware error.
37. Fixed HTTP/HTTPS boot failed.
38. Fixed system hang at 0xEE if the COM1/COM2 console redirection is disabled.

- 39. *Updated binaries for SMCOOBV2.00.17.*
- 40. *Fixed the memory serial number of SMBIOS type 17, which did not match the memory DIMM bar code.*
- 41. *Fixed the NVMe hotplug malfunction with BPN-NVMe5-F418-B6S6.*
- 42. *Masked ASPEED onboard VGA PCIe correctable error.*
- 43. *Corrected SLOT BDF for CPU port PE5.*

1.0 (09/21/2022)

- 1. *First release.*