## **BMC Firmware Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

<b>Product Name</b>	X13SET-G(C)
Release Version	1.00.13
<b>Build Date</b>	3/27/2023
<b>Previous Version</b>	1.00.11
<b>Update Category</b>	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol> <li>[v01.00.08 firmware] Redfish Automation test failed in system/NM.</li> <li>[Beta Release] NC-SI failed on AIOM Slot A1.</li> <li>AOC-S25G-b2S sensor does not show up on the location 10.</li> </ol>

## Release Notes from Previous Release(s)

## 1.00.11 (3/2/2023)

- 1. BMC GUI fan speed Low critical wrongly displayed.
- 2. [Web Function] VLAN ID default value should be preset to 1 and not empty.
- 3. [Redfish] failed to successfully change mode to BMCNM.
- 4. System keeps rebooting with POST message "PEI—IPMI Initialization" after AC cycle.
- 5. Network AOC item was not present in the web GUI page.
- 6. Information of AOC-A25G-i2SM displayed abnormally in the BMC web UI.
- 7. Health Status/Sensor reading/Link Status cannot be identified after updating to BIOS 20230224.

Product Manager		Date	