
## **BMC Firmware Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPG-AR
Release Version	1.01.44
Build Date	5/12/2023
<b>Previous Version</b>	1.01.38
<b>Update Category</b>	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. To improve compatibility with IPMIECO TC0002, 2036, TC2063, TC2076
New features	
Fixes	<ol> <li>Fixed: [155644] ECO 20899 01.00.48 [MEL] MEL log Description not quite matching SNMPv3 Auth Protocol/ Private Protocol.</li> <li>Fixed: [154331] [16721 ECO IPMI 01.01.24] Deleted IPv6 DNS to create a "IPV6 DNS server 0:0:0:0:0:0:0:0 was deleted unsuccessfully" entry in the Maintenance Event Log.</li> <li>Fixed: [154317] ECO 21603 01.00.15(02/24/2023) Function—To enable the user to click blink or insert HDD button when system lockdown mode. Fixed: [153387] ECO 18380 1.01.11 System Lockdown - To fix SystemLockdown Storage Monitoring Physical View Eject / Insert button not disabled.</li> <li>Fixed: [153407] ECO2089901.00.44(02/03/2023)—To resolve a conflict checking rule on "Remote User" and "Remote Groups" while click on "Save" button in AD/LDAP.</li> <li>Fixed: [155731] To fix Redfish Automation 1 failure.</li> <li>Fixed: [156317] STD 18605 01.01.13 (20230426) — Component Info: To fix expanded PSU Table Text Inconsistency.</li> </ol>



- 8. Fixed: [156190] ECO -- 20899 -- 01.00.52 –To fix failure to add valid Prefix length128 for Static Route List
- 9. Fixed: [156182] To fix "No MEL log after configure the Mouse Mode setting" issue.