

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SSL-N/NT
Release Version	01.01.03
Release Date	08/23/2023
Build Date	08/23/2023
Previous Version	01.00.18
Update Category	Recommend
Dependencies	BIOS Rev. 1.5
Important Notes	ECO #28611 BMC_H13AST2600-ROT-1401MS_20230823_01.01.03_STDsp.bin Please update IPMI with attached Flash Utility in package. If the IPMI firmware revision is earlier than 01.01.01, please do not select the “Preserve” check box during IPMI firmware update.
Enhancements	N/A
New features	N/A
Fixes	1. [SD5_5.16.0_b1044] Redfish credential bootstrapping test fail flash BIOS need key-in user and password on the H13SSL-NT 2. [SSM_5.4.0_b1211] The System Information test fail Processor:Current Clock Speed(MHz): 0 is abnormal on the H13SSL-NT 3. Fixes no generate MEL when setting Console Capture Video and Crash Screen Capture. 4. Fixes [MEL] generated MEL not quite match when adding SNMPv2 (based on MEL SPEC v1.03) 5. Fixes the provision failed issue.

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

01.00.18 (04/27/2023)

1. Fix boot exception
2. Fix Sensor naming to match with spec
3. Fix Chassis intrusion Reset button does not gray out when System Lockdown Mode is ON
4. Fine-tune I3C clock parameters, and make to be compatible with more DIMM models

01.00.14 (02/10/2023)

1. Enable IPMB
2. fixes read incorrect Power Status without AMD CPU in H13 Platform

01.00.09 (12/05/2022)

1. Improve the problem of SMBUS reading and writing NIC card

01.00.06 (11/15/2022) First release