

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SEDW-F
Release Version	2.1
Release Date	12/06/2023
Build Date	12/06/2023
Previous Version	1.5
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated base to AMI label 99 (Intel WW47 BKC). Supports Emerald Rapid CPU.2. Supported VPD data of Broadcom network adapter (BCM957416A4160).3. Created boot option for Rocky Linux and sles-secureboot OS automatically.4. Default disable OOB send replace DisplayName feature to avoid that the SUM OOB test fail problem.5. Fixed HostInterface On/Off test will drop in 4x times in UEFI Shell.
New features	None

Fixes	1. Resolved IPV6 "Preferred DNS server IP" and IPV6 "Alternative DNS server IP" which were not displayed correctly on the BIOS setup.
-------	--

Release Notes from Previous Release(s)

1.5 (10/18/2023)

1. Updated 5.32_EagleStreamCrb_EMR_OACOR_095 for BKC WW39.
2. Exposed "Page Policy."
3. After using SUM to load BIOS default, BBS can be restored to default.
4. New methodology for NVIDIA A30X GPU card sensor reading.
5. Updated secure boot KEK/DB to add new Microsoft certificate.
6. Fixed the issue of Preserving Secure Boot Keys.

1.4 (8/10/2023)

1. Updated Intel BKC SPR 2023_WW21 PLR2/3, Intel RC Version 103.D70.
2. Updated PCIe Leaky Bucket Expected BER and Error Threshold items default value.
3. Updated Seamless MCU capsule revision to 1.0b for PLR2/3.
4. Corrected wrong report of SMBIOS Type16.
5. Updated S3M_PCode_MCC_S3 for MCC timing issue.
6. Resolved some boards resetting repeatedly after use IPMI tool to reset NVRAM.
7. According to motherboard UP/DP/MP, the corresponding HBM SMBIOS type 17 device locator format is now used (UP : HBMIOx, DP/MP : Px_HBMIOx).
8. According to motherboard UP/DP/MP, the corresponding HBM memory format on BIOS setup is now used (UP : HBMIOx, DP/MP : Px_HBMIOx).
9. Fixed some VGA cards having no display under legacy mode.
10. Memory speed is now displayed as MT/s instead of MHz.
11. When RTC power loss happens, BIOS build time is configured to system time.
12. "Available Bitmap:" is now present in the BIOS configuration file.
13. Fix missing end tag (0x78) of VPD data when the VPD length is a multiple of 4 (0 base).

1.1 (01/19/2023)

1. Updated Intel BKC 2022 WW51 (5.29_EagleStreamCrb_OACOR_071_BETA).
2. Followed latest BIOS setup template, to hide the UPI3 feature in setup for UP projects.
3. Ensured there is no FWTS error relative to SRIO.
4. Followed latest BIOS setup template to expose Consistent Device Name Support.
5. Updated SmcOOB to add support for the Redfish update.
6. Exposed "CXL Security Level" and "CXL Header Bypass" for CXL.
7. Removed CPU2, CPU3, and CPU4, which were displayed under IIO Configuration in setup after restoring optimized defaults.
8. Resolved the issue that caused "Crow pass Numa node info is missing" to appear.

1.0a (10/20/2022)

1. Updated Intel BKC WW41 from AMI label 5.29_EagleStreamCrb_OACOR_065.

2. *Disabled Pre-Go S1.*
3. *Default enable TOKEN "SMC_HECI_HIDE_DELAY" (HECI-x hide delay) for all projects to fix BSOD issue.*
4. *Exposed "Equalization Bypass To Highest Rate."*
5. *Automatically hide ADDDC Sparing item with x8 width DIMM.*
6. *Updated DBX file to fix Secure Boot Bypass issue.*
7. *Enabled the BOOT Guard relate setting.*
8. *Followed the SMBIOS template to sync the chassis type from FRU0 to SMBIOS Type 03.*
9. *Fixed Memory serial number of SMBIOS type 17 that does not match the memory DIMM bar code issue.*
10. *Fixed the problem that the password could not be saved after the NVRAM module updated label 26. (Updated SmcOOB module to 2.00.15)*