## **BMC Firmware Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

<b>Product Name</b>	X13SCW-F			
Release Version	1.02.05			
<b>Build Date</b>	12/08/2023			
<b>Previous Version</b>	Beta Release			
<b>Update Category</b>	Recommended			
Dependencies	None			
Important Notes	None			
Enhancements	Support BIOS attribute name without seq num.			
	2. Added SPS version and Microcode version to firmware			
	2. Added 3r3 version and wherecode version to miniware			
	inventory.			
	3. Enhanced the GPU Redfish API value.			
New features	1. Added Property "Product" for /redfish/v1.			
	2. Enabled USB Lan 2 options feature (WEB).			
	2. Litabled OSB Latt 2 Options feature (WLB).			
Fixes	1. AOC card Thermal reading issue.			
	2. BMC Host Interface becomes "Disabled."			
	3. Added MEL after changing Host Interface "RNDIS Connection"			
	or "CDC-ECM Connection."			
	4. Opened JDK support.			
	5. Failed to Set LAN Auto Configuration DHCPv6Mode			
	Configuration			

- 6. Unable to load SMTP page.
- There is an extra backplane object on BMC "Firmware Management" page.
- 8. Operator cannot have Full Access to Event Log.
- Logging out with enabled SMTP alert will create three MEL entries.
- 10. SUM -- Failed to Set LAN Auto Configuration DHCPv6Mode Configuration.
- 11. Notifications (SNMP) in Help page are inconsistent with Actual WEB page.
- 12. Validated Access with OOB and No License should switch to newer UI behavior.
- 13. The NVMe temperature will sometimes be 45C.
- 14. License require behavior/message did not quite match with SW-PM definition.
- 15. Duplicated MEL when setup Dedicated Link Speed & 1G Full Duplex MEL did not match with option name.
- 16. When created RAID level 10/50/60(Span Depth=3), the "RAID level" information on the BMC Web GUI is incorrect.
- 17. [MEL-0104] was not listed after successful BMC update without all configurations preserved.
- 18. Set power limit 0 to Node Manager failed.
- 19. Should not be able to set invalid ipv6 DNS values using SMC IPMI Tool raw commands.
- 20. Toggling the system power will create repeated "Host FW password has been removed / auto-generated" entries in the MEL.
- 21. Enabled anti-rollback ID checking for non-RoT BIOS.
- 22. System Lockdown did not disable the Host Interface USB Connection radio buttons.
- 23. Couldn't find GPU data and status via redfish.