# **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFR-AN6
<b>Release Version</b>	01.02.00
Release Date	8/24/2023
<b>Previous Version</b>	01.01.21
<b>Update Category</b>	Recommended
Dependencies	N/A
Important Notes	IPMI Image: BMC_H12AST2600-ROT-E201MS_20230824_01.02.00_STDsp.bin IPMI Update Package: BMC_H12AST2600-ROT-E201MS_20230824_01.02.00_STDsp.zip
Enhancements	N/A
New features	N/A
Fixes	<ol> <li>[Fix] ECO 18380 01.01.21 SUM TC 0003 0010 2011 2020 2036 2037 2038 2039 2040 2041 fail</li> <li>[Fix] [SSM_5.4.0_b1211] The System Information test fail (Processor:Current Clock Speed is abnormal) on the H12SSW-AN6-P</li> <li>[Fix] [16728 ECO IPMI 01.01.24] SNMPv2 Community String name can be set with special characters</li> <li>[Fix] 16728 ECO IPMI 01.01.24] Syslog packets show (none) instead of the IP address when no hostname is set Copy Project Issue Link</li> <li>[Fix] [16721 ECO IPMI 01.01.24] Successfully deleting IPv6 DNS will always create a "IPV6 DNS server 0:0:0:0:0:0:0:0 was deleted unsuccessfully" entry in the Maintenance Event Log</li> <li>[Fix] ECO 18380 01.01.24(03/02/2023) Function Not generate MEL after changed LDAP or AD service setting</li> <li>[Fix] PWS Still Present In IPMI WebGUI After Pulling Out PWS Module</li> <li>[Fix] ECO 18380 01.01.25(04/14/2023) SMTP will send multi alert mail with</li> </ol>

- 9. [Fix] ECO -- 18380 -- 01.01.25(04/14/2023) -- [SUM] IPv4 DNS address will change to the other when modify BMC LAN configuration
- 10. [Fix] IPMIECO ATT test failed
- 11. [Fix] [AOC-SLG4-2H8M2] The "Product Name/Firmware Revision" of M.2 drive couldn't be displayed correct under the BMC WebUI/Storage Monitoring page.

#### Release Notes from Previous Release(s)

# 01.01.21 (1/11/2023)

- 1. Update i2cmap file for VRM
- 2. The system report P1\_VDDCR and P2\_VDDCR voltage going high during cburn test

### 01.01.09 (2/15/2022)

- 1. Sensor Reading UI Fail
- 2. [MB Rev1.10] FAN sensor detection are wrong.
- 3. [IPMI ECO v01.01.07] Remote Console Preview monitor function failed after press "Java plug-in" icon.
- 4. [MB Rev1.10] Front panel's Fail LED is not blinking when fan pin got removed.
- 5. [DVT] TDP Watts in IPMI Web GUI CPU information page is 0
- 6. [DVT] Unexpected duplicating FAN mode options
- 7. SATC redfish test fail Copy Project Issue Link
- 8. Duplicate Drives in IPMI WebGui
- 9. STD -- 18380 -- 01.01.05 -- [SUM] TC239 BIOS password will not preserve after run sum command "LoadDefaultBiosCfg"
- 10. STD -- 18380 -- 01.01.05 -- [redfish] version is mismatch with release note
- 11. IPMIECO ATT test failed.
- 12. GPU temperature display sequence is incorrect.
- 13. [BMC 1.01.03] There's an abnormal event without description during AC cycles.

### 01.00.23 (7/12/2021)

- 1. The Marvell controller(AOC-SLG2-2TM2) info and function are invalid in BMC WEB. Copy Project Issue Link
- 2. The AOC location info(AOC-AG-i2M) is N/A Copy Project Issue Link
- 3. The AOC location is not in sequence. Copy Project Issue Link
- 4. The sensor name "AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link
- 5. Opening and closing the HTML5 Remote Console Disables Remote Console

## 01.00.08 (1/28/2021)

- 1. Digital Battery Reading Check Fail
- 2. No AIOM sensor reading on IPMI GUI.

#### 01.00.00

First release.