

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	G1SMH-G
Release Version	01.02.26
Build Date	03/15/2024
Previous Version	01.02.09
Update Category	Recommended
Dependencies	BIOS R1.1a
Important Notes	BMC Image: BMC_SCMAS2600-ROT20-2501MS_20240315_01.02.26_STDsp.bin BMC Update Package: BMC_SCMAS2600-ROT20-2501MS_20240315_01.02.26_STDsp.zip *It is critical to follow the proper sequence when updating the BMC.
Enhancements	1. The firmware inventory webpage is slow when system is powered off. 2. Added support for Memory/GPU_x/MemoryMetrics. 3. Resolved issue where CPLD update failed sometimes. 4. Resolved the issue of the Backplane CPLD update being too slow.
New Features	N/A
Fixes	1. Resolved the issue where GPU page hung indefinitely. 2. Resolved the issue where no information was displayed in the GPU tab. 3. Resolved the issue where UID remained solid on after holding the UID button for more than 12 seconds. 4. Resolved the issue where IPMI Redfish automation check power supply version failed. 5. Resolved the issue where CPU temp sensor read "0" on one of the two nodes during cburn on or off. 6. Resolved the issue where all sensors reported "NA" during ON/OFF 7. Resolved the issue where the M.2 Sensor was dropping during power ON/OFF BPC 8. Resolved the issue where both nodes fail ONOFF with E1.S drives 9. Resolved the issue where the storage monitoring was inaccessible in the Web GUI. 10. Resolved the issue where the Storage Monitoring tab was missing.

- | | |
|--|---|
| | <ol style="list-style-type: none">11. Resolved the issue where the storage monitoring displayed incorrect drive information.12. Resolved the issue where CG1 systems with Dual BF3 GPUs showed two CPLD AOM 1 Bridge Board AOM-BB-GP102 entries13. Resolved the issue where the BIOS could not be updated when system was in BIOS setup.14. Resolved the issue where the GPU component info page was empty, and/Chassis/1/PCIeDevices/GPU[x] could not be found.15. Resolved the issue where the system failed to unmount the ISO image. |
|--|---|

Release Notes from Previous Release(s)

01.02.09 (11/10/2023)

Initial Release