

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2022 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|--|
| Product Name | X13DEM |
| Release Version | 2.1a SPS: 6.1.4.5 |
| Build Date | 03/20/2024 |
| Previous Version | 2.1 SPS: 6.1.4.5 |
| Update Category | Recommended |
| Dependencies | None |
| Important Notes | None |
| Enhancements | 1. Only applied HW VRM patch for 1.10 MB. 2. Updated BIOS revision to 2.1a. |
| New features | None |
| Fixes | None |

Release Notes from Previous Release(s)

2.1 SPS: 6.1.4.5 (8/25/2023)

1. Updated AMI label to 5.32_EagleStreamCrb_0AC0R_099_Beta for BKC WW47 EMR PV candidate.
2. Updated Eagle Stream Refresh Emerald Rapids Unified Patch Engineering Release - 2023 WW47.
3. Updated VROC SATA/sSATA/tSATA/VMD EFI driver to VROC PreOS v8.5.0.1096 PC.
4. Added VROC on Demand driver support.
5. Updated the SUM OOB module to SMCOOBV2.00.21 to support Redfish to replace the display name feature.
6. Used PCIe ASPM Support (Global) to control ASPM(PCH), PCI-E ASPM Support(IIO), Native ASPM(ACPI) option.
7. Hid "XPT Prefetch" in EMR CPU.
8. Supported VPD data of Broadcom Network Adapter.
9. Greyed out "Preferred DNS server IP" and "Alternative DNS server IP".
10. Implemented BIOS setup keyword search function.
11. Fixed HostInterface On/Off stress test that will drop in UEFI Shell intermittently.
12. Changed the FixedBootOrder BBS Group define start from COMMNE00 not COMMNE01.
13. Updated secure boot KEK/DB to add new Microsoft certificate.

14. Added X-AMI for "Disable Excluding Mem Below 1MB In CMR" and "TME-MT/TDX Key Split", and updated the strings to Camel-Case format.
15. Exposed "Page Policy".
16. Updated built-in SuperDiag to fixed issues, based on GIT_c4cc82130966861f501de64bd6bc4472ed05b2a5.
17. Default disabled OOB send replace DisplayName feature to avoid the SUM OOB test fail problem.
18. Made sure to assign a unique ID for NVME device.
19. Cleared RTC clear flag and IPMI RTC clear flag individually to prevent "Setup default has been loaded" still being displayed during next boot.
20. Resolved how IPV6 "Preferred DNS server IP" and IPV6 "Alternative DNS server IP" were not being displayed correctly on BIOS setup.
21. Fixed Secure erase malfunction.
22. Resolved the "BMC LAN Selection" setup item differing from the "LAN selection interface" under BMC WEB GUI.
23. Resolved how even if the 'Ipv6' is disabled in the BMC WEB GUI, the IPv6 address was still being displayed during the EarlyVideo stage.
24. Fixed when installing AOC-S25GC-12S on RSC-H-66G5L slot1, the network driver will show "Disconnect" under the BIOS page issue.

1.4 SPS: 6.0.5.46 (8/25/2023)

1. Updated AMI label to 5.31_EagleStreamCrb_EMR_OACOR_087.
2. Fixing the information of "Available Bitmap:" cannot be found in the BIOS Cfg file.
3. Updated BIOS revision to 1.4.
4. Updated Intel Server Platform Services SPS_E5_6.0.5.046 PLR3 HF for Eagle Stream Server Update 782193 Intel Server Platform Services SPS_E5_6.0.5.046 PLR3 HF for Eagle Stream Server.
5. Modified ME version strings, removed the "Manufacturer ID" string.
6. Fixed the missing end tag (0x78) of VPD data when the VPD length is multiple of 4. (0 base)
7. Expose the SATA1 menu for the PCH SATA M.2 setting to fix cannot enable RAID mode for the SATA M.2 device problem.
8. Memory speed should be MT/s, not MHz.
9. Fixed NVMe hot-plug malfunction on SYS-121H-TNR's last 8 ports issue.

1.3 SPS: 6.0.4.70 (6/1/2023)

1. Updated Intel BKC SPR 2023_WW13 PLR1, EMR 2023_WW19, Intel RC Version 101.D66.
2. Enhanced the solution for the error/warning message from dmidecode after a modification by AMIDE.
3. Removed first capital letter S from Micron type 17 serial number.
4. Updated options of Enhanced PPR from Disabled/Once/Persistent to Disable/Enable/Persistent.
5. Added support for 3'rd lan card VPD.(Mellanox)
6. Exported PCIe leaky bucket related items and add X-AMI ID.
7. Support SYS-121H-TNR with one BPN only sku.
8. Kept HBM SMBIOS type 17 structures.
9. Set PPIN default value to Unlock.
10. Rolled back GPNV module to fix type 15 disappear.
11. Added SuperDiag Launcher driver.

1.1 (1/20/2023)

1. Updated AMI label to 5.29_EagleStreamCrb_OACOR_071_BETA.

- 2. Updated SPS 6.0.4.25.
- 3. Updated 806F8 Intel(R) Processor SPR E-Stepping microcode 2B000161 and HBM B-Stepping microcode 2C000120.
- 4. Updated BIOS revision to 1.1.
- 5. Exposed "CXL Security Level" and "CXL Header Bypass" for CXL.
- 6. Enhanced memory map out feature.

1.0a (11/2/2022)

- 1. Updated Intel BKC 2022 WW43 (KIT #750947, Intel RC Version 90.D03).
- 2. Updated BIOS revision to 1.0a.
- 3. Supports SYS-221HE-FTNR system configuration.
- 4. Set PCIe PLL SSC enabled value from 0.3% to 0.5%.
- 5. Fixed AFU return error so it will stop running when using the /N or /clnevnllog command.
- 6. Followed Intel WW36 MOW to disable Pre-GO_S1 setting.
- 7. Followed BMC_Network_AOC_Monitoring_Spec_v2.2 to discard the action to send AIOM/AOC IO Module LAN MAC to BMC.
- 8. Updated SPS 6.0.3.271 2S PC Hotfix Release for Eaglestream Platforms
- 9. Added new feature to set BIOS_EXIT_UBOOT/BIOS_BOOT_OK at end of POST.
- 10. Fixed SST function, not work issue.
- 11. Fixed the memory serial number of SMBIOS type 17, did not match memory DIMM bar code.

1.0

- 1. First release.

Product Manager

Date