

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SSL-N/NT
Release Version	01.02.06
Release Date	05/10/2024
Build Date	05/10/2024
Previous Version	01.02.03
Update Category	Recommend
Dependencies	recommend
Important Notes	ECO #30010 BMC_H13AST2600-ROT-1401MS_20240510_01.02.06_STDsp.bin Please update IPMI with attached Flash Utility in package. If the IPMI firmware revision is earlier than 01.01.01, please do not select the "Preserve" check box during IPMI firmware update.
Enhancements	1.[PBID#166551] no BIOS & BMC option for Inventory Recover when no License key is activated
New features	N/A
Fixes	1. [PBID#175871] IPv6 Helpage has duplicate text "Please Note: Similarly,...the BMC should allocate a new IP address and discontinue the use of its previous IPv6 address 2. [PBID#171628] [GUI] — IPv4/IPv6 help page description is inconsistent with UI Spec define 3. [PBID#174573] IPv4 DNS Server IP behavior not match with error tips 4. [PBID#173425] error return when upload "TSIG .key" and "TSIG.private" with 0kb file on DDNS page is not specific 5. [PBID#175958] NTP timezone unexpectly changed after setting up primary address 6. [PBID#175700] SATC Redfish automation test failed 7. Fix MB provisioning feature broken in tee 0100.03.79 and 0100.03.80. 8. SMTP help page description is inconsistent with SPEC 9. IPv4/IPv6 help page description is inconsistent with UI Spec define 10. Fail to switch Remote Control interface from HTML5 to Java plug-in after do iKVM reset 11. After changing Network setting, Severity on MEL page becomes malfunction 12. Per AMD thermal design requirement, change TcIt,limit value to 95 13. Fix front panel over heart led fail 14. The MEL displayed when add user via WEB UI and SMCIPMITool does not match 15. Virtual Media error message of Path to Image has typo

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

01.02.03 (03/18/2024)

1. Fixes Current owner index is wrong after RA provision
2. fixes MEL-0135 displays more than 3 times
3. Fixes BMC cannot obtain IP
4. Fixes [163528] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM
5. Fixes [163845] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM
6. Fixes [163529] ECO — 21603 — 01.01.07(09/22/2023) — [MEL] — No related MEL when disable TSIG Authentication
7. [162844] STD -- 21603 -- 01.01.05 (2023/09/08) -- WEB -- MEL is incorrect after do ikvm reset
8. [162823] ECO -- 21603 -- 01.01.05 -- Remote Console Preview current interface button enabled
9. [160509] ECO — 21603 — 01.01.01(07/21/2023) — [MEL] — should non-set IPv4 DNS Server IP related MEL be shown when setup Hostname or not
10. [162260] ECO -- 21603 -- 01.01.03 -- SNMP(User) Auth/Private Key naming not match with MEL
11. [162262] ECO -- 21603 -- 01.01.03 -- [GUI] Password can't be reverse of the User name, error return "Oops! Something went wrong." not quit match with the situation
12. [162263] ECO -- 21603 -- 01.01.03 -- SNMPv3(Alert) Authentication/Encryption Protocol naming not match with MEL
13. Fix OTP flush error and should stop provision
14. [159725] [RoT] Update CPLD Golden image event log timestamp is incorrect
15. [160511] ECO -- 21603 -- 01.01.01(07/21/2023) -- Could not mount ISO via SMCIPMITool when Virtual Media does not mount any ISO or floppy
16. Support IPv6 enhancement spec. (Proposal for BIOS-BMC IPv6 inconsistency_V11.pptx)
17. Update AMD RAS crash dump to ADDC 1.8
18. [156498] ECO -- 21603 -- 01.00.18 -- [MEL] should non-set IPv4 DNS Server IP related MEL be shown when setup IPv6 DNS Server IP or not
19. [162843] [IPMI 1.01.05 ECO] IPMI display "PCIE PERR error" when inject memory UECC
20. [162842] [IPMI 1.01.05 ECO] IPMI display incorrect location when inject memory CECC
21. [151917] [AMD RAS][CH6] No show OS error log when execute "GMI3/xGMI3 Error Injection"

01.01.08 (10/06/2023)

1. Fixes Current owner index is wrong after RA provision
2. fixes MEL-0135 displays more than 3 times
3. Fixes BMC cannot obtain IP
4. Fixes [163528] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM
5. Fixes [163845] ECO — 21603 — 01.01.07(09/22/2023) — [SUM] — IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg" command via SUM
6. Fixes [163529] ECO — 21603 — 01.01.07(09/22/2023) — [MEL] — No related MEL when disable TSIG Authentication
7. [162844] STD -- 21603 -- 01.01.05 (2023/09/08) -- WEB -- MEL is incorrect after do ikvm reset
8. [162823] ECO -- 21603 -- 01.01.05 -- Remote Console Preview current interface button enabled
9. [160509] ECO — 21603 — 01.01.01(07/21/2023) — [MEL] — should non-set IPv4 DNS Server IP related MEL be shown when setup Hostname or not
10. [162260] ECO -- 21603 -- 01.01.03 -- SNMP(User) Auth/Private Key naming not match with MEL
11. [162262] ECO -- 21603 -- 01.01.03 -- [GUI] Password can't be reverse of the User name, error return "Oops! Something went wrong." not quit match with the situation
12. [162263] ECO -- 21603 -- 01.01.03 -- SNMPv3(Alert) Authentication/Encryption Protocol naming not match with MEL
13. Fix OTP flush error and should stop provision
14. [159725] [RoT] Update CPLD Golden image event log timestamp is incorrect
15. [160511] ECO -- 21603 -- 01.01.01(07/21/2023) -- Could not mount ISO via SMCIPMITool when Virtual Media does not mount any ISO or floppy
16. Support IPv6 enhancement spec. (Proposal for BIOS-BMC IPv6 inconsistency_V11.pptx)
17. Update AMD RAS crash dump to ADDC 1.8
18. [156498] ECO -- 21603 -- 01.00.18 -- [MEL] should non-set IPv4 DNS Server IP related MEL be shown when setup IPv6 DNS Server IP or not
19. [162843] [IPMI 1.01.05 ECO] IPMI display "PCIE PERR error" when inject memory UECC
20. [162842] [IPMI 1.01.05 ECO] IPMI display incorrect location when inject memory CECC
21. [151917] [AMD RAS][CH6] No show OS error log when execute "GMI3/xGMI3 Error Injection"

01.00.18 (04/27/2023)

1. Fix boot exception
2. Fix Sensor naming to match with spec
3. Fix Chassis intrusion Reset button does not gray out when System Lockdown Mode is ON
4. Fine-tune I3C clock parameters, and make to be compatible with more DIMM models

01.00.14 (02/10/2023)

1. Enable IPMB
2. fixes read incorrect Power Status without AMD CPU in H13 Platform

01.00.09 (12/05/2022)

1. Improve the problem of SMBUS reading and writing NIC card

01.00.06 (11/15/2022) First release