BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPG-OA6-GD2
Release Version	1.05.08
Build Date	08/02/2024
Previous Version	1.04.11
Update Category	Recommended
Dependencies	None
Important Notes	 SMC-2024010010 Command Injection attack. SMC-2024010011 XSS attack.
	• SIVIC-2024010011 ASS attack.
	• (CVE-2023-33413) SMC-2024010012 Command Injection attack.
	The BMC configuration file generated in BMC firmware older
	than Rev. 01.04.XX can't be imported.
Enhancements	 [ENGINEERING] – Resumed pending task now possible through Web GUI. [ENGINEERING] – Redfish should allow external account service password length of more than 20. [ENGINEERING] – Added RSA2048 key for license server from new IT HSM.
New features	 [ENGINEERING] – Redfish Upgrade 2021.2, RF1.14. [ENGINEERING] – Upgraded SEL to 1.38 and merged SEL search method to one function. [ENGINEERING] – Redfish support BMC each field v1.33/ v1.34.

	4. [ENGINEERING] – Supported AOC-S400G-B1C.
	1. [ENGINEERING] – OSS Requirements.
	2. [ENGINEERING] – Removed Action of ResetToDefault
	parameter "PreserveNetwork".
	3. Sensor's threshold \'LowNR\', \'Low CT\' and \'High NR\' show
	empty for Temperature Type.
	4. [ENGINEERING] – Avoided wrong string and etag format in
	Redfish, and corrected Redfish API deprecate and create.
	5. (CVE-2024-36435) SMC-2023110008 Buffer Overflow
	vulnerability.
	[Security] GetValue does not control length limit and caused
	stack buffer write overflow at X12DPG-OA6.
	6. [ENGINEERING] – Made PreserveNetwork backward compatible
	as Redfish 2020.
Fixes	7. [Security] The vulnerability of XSS attack on KVM help page at
i mes	X14SBM.
	[Security] The XSS attack on local storage value at X12STW.
	8. DDNS accepting invalid characters.
	9. [ENGINEERING] – Fixed LAN setting will change when rebooting
	BMC.
	10. Redfish @odata.etag properties does not include surrounding
	"" double quotes.
	11. [ENGINEERING] – Updated Fan list sort rule.
	12. [ENGINEERING] – The System button of Dashboard has no
	reaction.
	13. [ENGINEERING] – Updated slot format of Physical Storage view.
	14. [ENGINEERING] – Adjusted license of OemDumpService.Collect.
	15. [ENGINEERING] – Updated the SSDP Redfish version and fixed
	possible exception.

- 16. DDNS showing incorrect error message.
- 17. FAN icon does not change to Red Critical when FAN failed happened on BMC WebUI.
- 18. Misspelled "necessary".
- [ENGINEERING] EventService RedfishEvent Https allowed selfsigned CA.
- 20. [ENGINEERING] X12 ALL sensor N/A in BMC 01.04.15.
- 21. When a license is required, clicking Cancel redirects users to dashboard. Should stay on same page, not redirect, or redirect to appropriate page for better user experience.
- 22. Updating the Backplane, Midplane, Fan/CPU/AIOM/AOM board CPLD all should now present MEL ID with the MEL.
- 23. [GUI] "BMC Reset" help info page description is inconsistent with UI Spec and BMC web.
- 24. SNMP v3 description incorrect on the HELP page.
- 25. [ENGINEERING] Web UI Prompts 11162023
- 26. [ENGINEERING] Supported AOC-E810-XXVDA4.
- 27. [ENGINEERING] Upgraded MEL to 1.07 and added MEL 70 and 368.
 - Recorded wrong MEL number when uploaded IPMI configunsuccessfully.
- 28. DNS Server 1 and 2 IP ability to be set to duplicate values via SMCIPMITool.
- 29. Web Function 0.0.0.0 is not allowed to be saved in 'Server Address'.
- 30. Server Address field can fill in over 255 characters does not match with the Spec definition. (AD and LDAP)
- 31. It allows class D, E of IPv4 addresses for DNS Server IP setting.
- 32. Failed to mount an ISO file with IPv6 address (ExitCode:148).
- 33. "SerDes Temp" can't display temperature under BMC GUI.