

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DEG-M</b>
<b>Release Version</b>	<b>2.4 SPS: 6.1.4.47</b>
<b>Build Date</b>	<b>08/20/2024</b>
<b>Previous Version</b>	<b>2.2 SPS: 6.1.4.5</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated AMI label to 5.32_EagleStreamCrb_0ACOR_105_BETA for uPLR2.</li><li>2. Filled DUID with UUID to avoid having all systems' DUID in IPv6 DHCP be the same.</li><li>3. Implemented workload profile.</li></ol>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Overwrote AmiPcdChassisType to sync SYS_CHASSIS_TYPE_1 setting.</li><li>2. Resolved the issue where UEFI hard drive was not the first boot priority after IPMI started a PXE boot once, then installed UEFI OS.</li></ol>

**Release Notes from Previous Release(s)**

**2.2 SPS: 6.1.4.5 (03/01/2024)**

1. Updated AMI label to 5.32\_EagleStreamCrb\_0ACOR\_101 for BKC 2024\_WW05.
2. Removed report the un-use boot device group in the Redfish BBS.
3. Enhanced Security Erase module, updated version to v1.02.
4. SUM get duplicate Super Guardians Form in lists.
5. Updated EDK2 NetworkPkg for AMI SA50218.
6. Updated AMITSE module for AMI SA50230.
7. Updated AMITSE module for AMI SA50216.
8. Removed the "System Firmware Error(POST ERROR)" error log to BMC and "EFI 01030006" in BIOS event log. (Refer to Purley svn 1896.)
9. Added FixedBootOrder Group boot device default value.
10. Fixed how the BIOS Setup could not set stateful mode of IPv6.
11. Fixed the system hang at OS Ubuntu with 8593Q.
12. Fixed SSM HTTPS boot fail.

**2.1 (12/12/2023)**

1. First release.

---

Product Manager

---

Date