

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPU-6
Release Version	1.05.02
Build Date	10/30/2024
Previous Version	1.04.08
Update Category	Recommended
Dependencies	None
Important Notes	<ul style="list-style-type: none">• SMC-2024010010 Command Injection attack.• SMC-2024010011 XSS attack.• (CVE-2023-33413) SMC-2024010012 Command Injection attack.• The BMC configuration file generated in BMC firmware older than Rev. 01.03.14 can't be imported.
Enhancements	<ol style="list-style-type: none">1. Upgraded OpenSSH from 9.3p2 to 9.8p1.
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed unexpected "The path of Process SSHD is not correct" MEL message. Updated tee.bin to 0000.00.32.2. NTP disabled, no date, time, and time zone control in BMC.3. WebUI — TC4017- Fixed IPMI IP will be replaced or lost. [178393] CombinedECO SAA- TC0005 — Connection through dedicated LAN with static IP. [178393] CombinedECO SAA- TC0007 — Connection through on-board LAN1 with static IP.4. [Function] — General Hostname field can fill in 64 characters which does not match with the Spec definition.

	<p>5. iKVM — When open more than maximum 4 sessions, return message is not follow SPEC definition.</p>
--	---